

# Heavy Equipment Condition Report:

## Asset Information:

Equipment Type: Loader

Other: \_\_\_\_\_

Unit No: 12681 / 630045

Engine Information:

Year: 2004

Year: \_\_\_\_\_

Make: Kawasaki

Make: \_\_\_\_\_

Model: 90ZV

Model: \_\_\_\_\_

HP: \_\_\_\_\_

VIN/SN: 90C45007

SN: \_\_\_\_\_

Miles/Hrs.: \_\_\_\_\_

Fuel Type: Diesel

## Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: \_\_\_\_\_

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: \_\_\_\_\_

Control Station Type: Enclosed Cab

AC/Heat: Yes

AC/Heat working: Could not confirm

Additional Equipment: The Cab to this asset was locked. It could not be opened at the time of the inspection.

## Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: \_\_\_\_\_

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: \_\_\_\_\_

Front: \_\_\_\_\_

Rear(s): \_\_\_\_\_

## Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes: