

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 13027 / 791105

Engine Information:

Year: 2001

Year: _____

Make: Volvo

Make: Volvo

Model: L150D

Model: TD 103KCE

HP: _____

VIN/SN: V62632

SN: _____

Miles/Hrs.: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: _____

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes

AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: Rail car coupling attachment

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: