

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 13017 / 792175

Engine Information:

Year: 2001

Year: _____

Make: Volvo

Make: _____

Model: L150D

Model: _____

HP: _____

VIN/SN: L150DV26243

SN: _____

Miles/Hrs.: 6758

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Poor - Wheel Condition is damaged and will need to be replace

Tire Size:

Front: 26.5R25

Rear(s): 26.5R25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: Volvo 93703 Loader Bucket

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: