

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Haul Truck

Other: _____

Unit No: 10191 / 775560

Engine Information:

Year: 1999

Year: _____

Make: Caterpillar

Make: _____

Model: 775D

Model: _____

HP: _____

VIN/SN: 8AS00174

SN: _____

Miles/Hrs.: _____

Fuel Type: _____

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Poor - Interior has severe damage and/or tears beyond normal wear.

Exterior Condition: Poor - Major body damage.

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: Could not confirm

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: