Heavy Equipment Condition Report:

Asset Information:		
Equipment Type:	Backhoe	
Other: _		
Unit No: 12794 / 623427		Engine Information:
Year: 2002		Year:
Make: Cat		/lake:
Model: 416D	N	odel: HP:
VIN/SN: BP06187		SN:
Miles/Hrs.: Non operational		Type: Diesel
Asset Condition:		
Mechanical Condition:	•	ate and is in need of repair.
Interior Condition:	Fair - Interior is heavily wor	
Exterior Condition:	Fair - Visible dents and scra	
Hydraulics are Functional:	Could not confirm	Hydraulic Leaks Present: Could not confirm
Unit Moves FWD/REV:	Neither	
All Attachments Articulate	 -	otes:
Control Station Type:	Canopy AC/	Heat: No AC/Heat working: N/A
Additional Equipment: _		
Chassis:		
Demontrain Tunos		SSIS:
Powertrain Type:	4WD	
Propulsion Type:		
Track Condition:	The state of the s	
Wheel Condition:		amaged and will need to be replace
Tire Size:	Front: 11L-16	Rear(s): 19.5-24
ومساو وينجو المحدثينات المحدث	Attach	
Are there additional attachme	ints that are not currently	connected to this asset?
Describe: Buckts		- **
Type: Front bucket		1.25yd 89in
Type: Rear bucket	D6	tails: 36in
Additional Notes:		
Non operational		