

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 13026 / 621579

Engine Information:

Year: 2003

Year: _____

Make: Cat

Make: Caterpillar

Model: 980G

Model: 3406E-DI-TA

HP: 346

VIN/SN: AWH01034

SN: BET02980

Miles/Hrs.: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: Could not confirm

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: _____

Track Condition: _____

Wheel Condition: Poor - Wheel Condition is damaged and will need to be replace

Tire Size:

Front: 29.5r25

Rear(s): 29.5r25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: none

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

Non operational