

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 12559 / 789523

Engine Information:

Year: 2001

Year: _____

Make: Cat

Make: _____

Model: 980G

Model: _____

HP: _____

VIN/SN: 2kr04293

SN: _____

Miles/Hrs.: Non operational

Fuel Type: _____

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Poor - Interior has severe damage and/or tears beyond normal wear.

Exterior Condition: Poor - Major body damage.

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: Could not confirm

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Poor - Wheel Condition is damaged and will need to be replace

Tire Size:

Front: 29.5r25

Rear(s): 29.5r25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: none

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

Non operational