

# Heavy Equipment Condition Report:

## Asset Information:

Equipment Type: Loader

Other: \_\_\_\_\_

Unit No: 10671 / 715284

Engine Information:

Year: 1999

Year: \_\_\_\_\_

Make: Caterpillar

Make: \_\_\_\_\_

Model: 992G

Model: \_\_\_\_\_

HP: \_\_\_\_\_

VIN/SN: 7HR00299

SN: \_\_\_\_\_

Miles/Hrs.: \_\_\_\_\_

Fuel Type: Diesel

## Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Poor - Interior has severe damage and/or tears beyond normal wear.

Exterior Condition: Poor - Major body damage.

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: \_\_\_\_\_

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: \_\_\_\_\_

## Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: \_\_\_\_\_

Wheel Condition: Poor - Wheel Condition is damaged and will need to be replace

Tire Size: \_\_\_\_\_

Front: \_\_\_\_\_

Rear(s): \_\_\_\_\_

## Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes: