Heavy Equipment Condition Report:

	ASSE	Limormati	OII.		
Equipment Type: _	Excavator				
Other:					
Unit No: 11820 / 1223951			Engine Infor	mation:	
Year: 2014		Year:			
Make: John Deere		Make:			
Model: 470G		Model:			HP:
VIN/SN: 1FF470GXKCE4705	548	SN:			
Лiles/Hrs.:		Fuel Type:	Diesel		
	Ass	et Conditio	n:		
Mechanical Condition:	Good - Starts and ope	erates; Some p	arts may require repa	ir or replac	ement soon.
Interior Condition:	Good - Damage is limited to normal wear and minor scratches.				
Exterior Condition:	Good - Minor dings ar	nd scratches			
Hydraulics are Functional:	Could not confirm	Hydra	ulic Leaks Present:	Could not	confirm
Unit Moves FWD/REV:	Neither				
All Attachments Articulate	Could not confirm	Notes:			
Control Station Type:	Enclosed Cab	AC/Heat:	Yes AC/Heat v	working:	Could not confirm
Additional Equipment:	Seller claims unit was	running wher	n staged in this area of	the proper	rty
		Chassis:			
Powertrain Type:	2WD				
Propulsion Type:	Track, Metal				
Track Condition:	Good - Track condition shows normal wear from use				
Wheel Condition:					
Tire Size:	Front:		Rear(s):		
	A	ttachments	5		
Are there additional attachme	ents that are not curr	ently connec	ted to this asset?		
Describe:					
Туре:		Details:			
Туре:	Details:				
Additional Notes:					