

# Heavy Equipment Condition Report:

## Asset Information:

Equipment Type: Excavator

Other: \_\_\_\_\_

Unit No: 10823 / 989461

Engine Information:

Year: 2009

Year: \_\_\_\_\_

Make: Hitachi

Make: \_\_\_\_\_

Model: ZX450LC

Model: \_\_\_\_\_

HP: \_\_\_\_\_

VIN/SN: FF016JQ011473

SN: \_\_\_\_\_

Miles/Hrs.: \_\_\_\_\_

Fuel Type: Diesel

## Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: Could not confirm

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: \_\_\_\_\_

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: \_\_\_\_\_

## Chassis:

Powertrain Type: 2WD

Propulsion Type: Track, Metal

Track Condition: Good - Track condition shows normal wear from use

Wheel Condition: \_\_\_\_\_

Tire Size: \_\_\_\_\_

Front: \_\_\_\_\_

Rear(s): \_\_\_\_\_

## Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes: