## **Vehicle Condition Report:**

|                           |                                      | ncie imorn              | iation.            |           |            |              |
|---------------------------|--------------------------------------|-------------------------|--------------------|-----------|------------|--------------|
| Vehicle Type:             | Cargo Van                            |                         |                    |           |            |              |
| Other:                    |                                      |                         |                    |           |            |              |
| Unit No: PB238409         |                                      |                         | Engi               | ne Inforn | nation:    |              |
| <b>Year:</b> 2015         |                                      | Year:                   | 2015               |           |            |              |
| Make: Ford                |                                      | Make:                   | Ford               |           |            |              |
| Model: Transit 250        |                                      | Model:                  | 3.7                |           |            |              |
| VIN/SN: 1FTNR2CM2FKB19    | 557                                  | SN:                     |                    |           |            |              |
| Miles: Unknown            |                                      | Fuel Type:              | Gasoline           |           |            |              |
| Vehicle Condition:        |                                      |                         |                    |           |            |              |
| Mechanical Condition:     | Poor - Will not start                | or operate ar           | nd is in need of r | epair.    |            |              |
| Interior Condition:       | Fair - Interior is heavily worn.     |                         |                    |           |            |              |
| Exterior Condition:       | Fair - Visible dents a               | and scratches           |                    |           |            |              |
| Condition Comments:       |                                      |                         |                    |           |            |              |
| -                         |                                      |                         |                    |           |            |              |
| Fugino Digulacomente      | 2.7 Litous Cu                        | onkahaft /\/            | Inline Bayon       | \ /       |            | Culindons    |
| Engine Displacement:      |                                      | anksnait (v,            | Inline, Boxer)     |           |            | Cylinders: 6 |
| Power Windows:            | Yes                                  | 40 / 111                | Power Locks:       | Yes       |            |              |
| Air Conditioner / Heat:   | Yes                                  | -                       | Functional:        |           |            |              |
| Transmission:             | Automatic Number of Manual Speeds: 6 |                         |                    |           |            |              |
| Unit Moves FWD/REV:       | Neither                              |                         |                    |           |            |              |
| Four Wheel Drive (4x4):   | No                                   |                         | Functional: _      | Could No  | ot Confirm |              |
| Additional Equipment:     |                                      |                         |                    |           |            |              |
| <u>-</u>                  |                                      |                         |                    |           |            |              |
|                           |                                      |                         |                    |           |            |              |
|                           |                                      | Chassis                 |                    |           |            |              |
| Suspension:               | Spring                               | Notes:                  |                    |           |            |              |
| Wheelbase:                | 148                                  | GVWR:                   | 9000               | Front:    |            | Rear(s):     |
| Tire Size:                | Front:                               | 235/65r16               |                    | Rear:     | 235/65r16  | <u> </u>     |
| Comments:                 |                                      |                         |                    |           |            |              |
|                           |                                      |                         |                    |           |            |              |
| Cargo / Passenger Vans    |                                      |                         |                    |           |            |              |
| Passenger Van Seating:    | Rows                                 | · / · · · · · · · · · · | ,                  |           |            |              |
| . assenger van seating.   |                                      |                         |                    |           |            |              |
| Cargo Van Box Dimensions: | Length:                              | 126in                   | Width:             | 60in      | Height:    | 79in         |
| Additional Notes:         | Length.                              | 120111                  | JVIGCII            |           |            | 7,5111       |
| Additional Notes.         |                                      |                         |                    |           |            |              |
| -                         |                                      |                         |                    |           |            |              |