Fork Lift Condition Report:

			FORKIITT INTO	rma	tion	
Unit No: B1	B18852				Engine Information:	
Year: 20	2017 Year:			ear:	2017	
Make: Co	Combilift Make:			ke:	Mitsubishi	
Model: C1	C12000XL Model:			del: ¯	TD03-07G	HP:
VIN/SN: 36	36184 SN :			SN:	170117028	
Miles/Hrs.: 74	136		Fuel Ty	pe:	Diesel	
Forklift Condition						
Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.						
Interi	ior Condition:	Fair - Inte	- Interior is heavily worn.			
Exterior Condition: Fair - Visible dents and scratches						
Control Station:						
Steering Control Operationa			Yes		Notes:	
	Control Statio	n Type:	Canopy			
AC/H	Heat (If enclose	d Cab):	No		AC/Heat Functional:	
P	Additional Equi	pment:				
Hydraulics:						
Hydraulics ar	re Functional:	Yes			ulic Leaks Present: No	
•	es FWD/REV:	Both		,		
All Attachments Articulate Yes			Notes:			
Comments:						
Undercarriage:						
Powe	wertrain Type: 3WD				Drivetrain is functional: Yes	
	Tire Type:	Cushion			Non-Marking?	
	Comments: _					
Mast:						
	Mast Type:	2-Stage	IVIASI			
May		159	 In. L	0.440	wod Mast Hoight:	In.
	lax Lift Height: 159 Fork Length: 48		.'''. In.	Lowered Mast Height:		—""
	rork Length k Positioner:	No No	Notes:			
FOIR	Side Shift:	No	Notes:			
	Scales:	No	Notes:			
Othar At	ttachments:	No				
Other A	ttatiiiieiits:	INU	Notes:			