

Truck Tractor Condition Report:

Equipment Information:

Unit No:	B17616	Engine Information:	
Year:	2018	Year:	2018
Make:	Peterbilt	Make:	PACCAR
Model:	567	Model:	MX-13
VIN/SN:	1XPCDP9X8JD463782	SN:	Y134168
KM/Hrs.:	192618	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen **Engine Displacement:** 12.9 **Number of Cylinders** 6

Sleeper (if Applicable): Length: # of Bunks: **Aux Power Unit?**

Additional Equipment:

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual **Number of Speeds:** 10

Truck Moves FWD/REV: Both

Comments: Transmission scratches between 5th and 6th gear. Otherwise runs as it should.

Chassis:

Frame Rails: **Notes:**

Suspension: Spring **Notes:**

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: 53,200 **Front Axel:** 13,200 **Rear(s):** 40,000

Tire Size: **Front:** 295/75RT22.5 **Rear(s):** 295/75RT22.5

Comments:

Specialized Equipment:

Type: **Details:**

Type: **Details:**

Notes:

Notes: