

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Crane, Deck

Other: _____

Unit No: 60

Year: 2017

Make: Broderson

Model: IC-80-3J

VIN/SN: 70932680

Miles/Hrs.: 726

Engine Information:

Year: 2016

Make: KEM

Model: 430-DF-BROD

HP: _____

SN: 201602028

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: _____ AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: _____

Front: 10.00-15

Rear(s): 10.00-15

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: