

Fork Lift Condition Report:

Forklift Information

Unit No:	_____	Engine Information:	_____
Year:	2023	Year:	_____
Make:	Linde	Make:	Deutz
Model:	H35T	Model:	_____ HP: _____
VIN/SN:	H21202M01884	SN:	_____
Miles/Hrs.:	_____	Fuel Type:	Diesel

Forklift Condition

Mechanical Condition:	Poor - Will not start or operate and is in need of repair.
Interior Condition:	Good - Damage is limited to normal wear and minor scratches.
Exterior Condition:	Fair - Visible dents and scratches

Control Station:

Steering Control Operational:	Could not confirm	Notes:	_____
Control Station Type:	Canopy		
AC/Heat (If enclosed Cab):	No	AC/Heat Functional:	_____
Additional Equipment:	_____		

Hydraulics:

Hydraulics are Functional:	Could not confirm	Hydraulic Leaks Present:	Could not confirm
Unit Moves FWD/REV:	Unknown		
All Attachments Articulate	Could not confirm	Notes:	_____
Comments:	unit needs new batteries		

Undercarriage:

Powertrain Type:	2WD	Drivetrain is functional:	Could not confirm
Tire Type:	Solid Pneumatic	Non-Marking?	_____
Comments:	_____		

Mast:

Mast Type:	3-Stage		
Max Lift Height:	132	In.	Lowered Mast Height: _____ In.
Fork Length:	38	In.	
Fork Positioner:	No	Notes:	_____
Side Shift:	Yes	Notes:	_____
Scales:	No	Notes:	_____
Other Attachments:	No	Notes:	_____