

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: _____

Other: _____

Unit No: A020

Year: 2015

Make: Roadtec

Model: SX6E

VIN/SN: 79688557

Miles/Hrs.: 4971

Engine Information:

Year: _____

Make: Cummins

Model: _____

SN: _____

Fuel Type: Diesel

Starts and Runs:

Yes

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic

Track Condition: N/A

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size:

Front: 28L-26

Rear(s): 28L-26

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: Roadtec Drum SN: CHX6-100-111

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: