

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Excavator

Other: _____

Unit No: A021

Year: 2006

Make: Gradall

Model: XL4100 II

VIN/SN: 210018048

Miles/Hrs.: 50922

Engine Information:

Year: _____

Make: _____

Model: _____

SN: _____

Fuel Type: Diesel

Starts and Runs:

Yes

HP: _____

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 2WD

Propulsion Type: Wheel, Pneumatic

Track Condition: N/A

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size:

Front: 385/65R22.5

Rear(s): 11R22.5

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: Gradall Chassis Cab SN: T8381E661 / Gradall Upper Cab SN: T8377M1269

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: