

Trailer Condition Report:

Equipment Information:

Unit No: 563

Year: 2011

Make: Central Hitch & Equipment

Model: Pro Pull

VIN/SN: 5WJUT2021BL000563

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Physical Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: 27,600

Suspension: Spring

Tire Size: 7.50R16LT

Sliding Tandem Axle: No

Braking: _____

Comments: _____

Deck

Hitch Type: Pintle

Dimensions: _____ Length: 20Ft _____ Width: 8Ft _____

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: Trailer has been staged for an extended period of time. Heavy rust, deck boards show damage and rot.

Notes: _____