

# Truck Tractor Condition Report:

## Equipment Information:

|          |                   |                     |         |
|----------|-------------------|---------------------|---------|
| Unit No: | _____             | Engine Information: | _____   |
| Year:    | 2013              | Year:               | 2013    |
| Make:    | Freightliner      | Make:               | Detroit |
| Model:   | Cascadia          | Model:              | DD13    |
| VIN/SN:  | 1FUJGBDV6DLBW4029 | SN:                 | _____   |
| KM/Hrs.: | 587475            | Fuel Type:          | Diesel  |
|          |                   | HP:                 | _____   |

## Equipment Condition:

**Mechanical Condition:** Good - Starts and operates; Some parts may require repair or replacement soon.

**Interior Condition:** Fair - Interior is heavily worn.

**Exterior Condition:** Fair - Visible dents and scratches

**AC/Heat Functional:** Yes

**Leaks Present:** Not Seen

**Engine Displacement:** 12.8

**Number of Cylinders** 6

**Sleeper (if Applicable):** Length: \_\_\_\_\_

**# of Bunks:** \_\_\_\_\_

**Aux Power Unit?** \_\_\_\_\_

**Additional Equipment:** \_\_\_\_\_

## Transmission:

**Transmission Make:** Fuller

**Auto / Manual:** Automatic

**Number of Speeds:** \_\_\_\_\_

**Truck Moves FWD/REV:** Both

**Comments:** \_\_\_\_\_

## Chassis:

**Frame Rails:** Double

**Notes:** \_\_\_\_\_

**Suspension:** Air

**Notes:** \_\_\_\_\_

**Wheel Base:** \_\_\_\_\_ in.

**Axle Weight Ratings (LBS):** GVWR: 52,000 Front Axel: 12,000 Rear(s): 40,000

**Tire Size:** Front: 11R22.5

**Rear(s):** 11R22.5

**Comments:** \_\_\_\_\_

## Specialized Equipment:

**Type:** \_\_\_\_\_ **Details:** \_\_\_\_\_

**Type:** \_\_\_\_\_ **Details:** \_\_\_\_\_

**Notes:** \_\_\_\_\_

**Notes:** \_\_\_\_\_