

# Vehicle Condition Report:

## Vehicle Information:

**Vehicle Type:** Box Truck

**Other:**

**Unit No:** MX2016

### Engine Information:

**Year:** 2015

**Year:** 2015

**Make:** Freightliner

**Make:** Cummins

**Model:** M2 106

**Model:** CM2350A

**VIN/SN:** 3ALACWDT1GDGW0835

**SN:** 4239982

**Miles:**

**Fuel Type:** Diesel

## Vehicle Condition:

**Mechanical Condition:** Poor - Will not start or operate and is in need of repair.

**Interior Condition:** Good - Damage is limited to normal wear and minor scratches.

**Exterior Condition:** Fair - Visible dents and scratches

**Condition Comments:** engine needs work

**Engine Displacement:** 6.7 **Liters. Crankshaft (V, Inline, Boxer)** **Cylinders:** 6

**Power Windows:** No **Power Locks:** No

**Air Conditioner / Heat:** Yes **AC / Heat Functional:** Could not confirm

**Transmission:** Automatic **Number of Manual Speeds:**

**Unit Moves FWD/REV:** Neither

**Functional:**

**Four Wheel Drive (4x4):** No

**Additional Equipment:** Hydraulic Tailgate lift

## Chassis:

**Suspension:** Spring

**Notes:**

**Wheelbase:**

**GVWR:** 26000

**Front:** 10000 **Rear(s):** 18000

**Tire Size:**

**Front:** 11R22.5

**Rear:** 11R22.5

**Comments:**

## Cargo / Passenger Vans

**Passenger Van Seating:** Rows

**Cargo Van Box Dimensions:** Length: 30' Width: 8' Height: 10'

**Additional Notes:**