

Trade Condition Report

Traded Entity: Kerrville Police Dept – Unit 1314 Date of Inspection: 9/10/24

Vehicle Year: 2006 Make: Chevy Model: Impala Series: LS

Color: Silver Mileage: 115,552 Cylinders: V6 Motor(5.0, 4.3, 5.7etc)_____

Expected Mileage at Trade Date: 115,552 General Condition: x Good ___ Fair ___ Poor ___ Salvage

VIN: 2 G 1 W B 5 5 K 6 6 9 2 0 9 1 3 3

Comments

Windshield: ___ Cracked x Not Cracked _____

Windshield Chips: x None ___ 1 ___ 2 ___ 3 ___ 4 _____

Condition of Tires: ___ Poor x Good ___ New _____

Mechanical Condition: ___ Poor x Good ___ Very Good Evap leak error code – Evap purge valve. Avg cost \$323-\$380

Interior: ___ Poor ___ Good x Very Good _____

Exterior: ___ Poor x Good ___ Very Good Minor dings/scrapes. Bubbling tint rear window.

Check all that Apply: x Pwr Door Locks x Pwr Windows x Pwr Seats x Cruise x AM/FM ___ AM/FM Cass

x AM/FM CD x A/C(Blows Cold) ___ Smoker x Non-Smoker x Spare ___ Jack x Owner's Manual

___ Alloy Wheels x Window Tint x 2 sets of keys Lettering/Decals: ___ Removed ___ Traded with Decals

Holes exterior on roof/trunk: ___ Plug Holes x Holes exposed Holes interior ___ holes ___ no holes

Equipment Staying: _____

Equipment Removed: Radio, console, lights, siren, system control module, wig wags

Person Completing Form: Jennette Dennis Trade Title status: Inventory Control Analyst

Additional Comments: _____

