

Vehicle Inspection Form

Inventory ID: 56	Asset Number:	Fair Market Value:
Short Description: Year <u>2006</u> Make <u>CHRYSLER</u> Model <u>300</u>		
VIN: 2 C 3 K A 4 3 R 7 6 H 4 6 1 0 9 6		
Odometer: 1 7 5 9 9 3 ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____		
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>2.7 L, V 6</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>SEE ATTACHED</u> This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>04/22/2024</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>SEE ATTACHED</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>SILVER</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: <u>OK</u> Tread: _____ #Flat <u>0</u> Hubcaps # <u>4</u> Major Damage to: _____ Additional Damage: <u>PAINT BUBBLING ON REAR PASSENGER WHEEL WELL</u> Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>GRAY</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>WORN</u> Damage to Dash/Floor: _____ Radio: ☐ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☒ No AC Air Bags: ☐ Driver's Side ☐ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: <u>N/A</u> Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: <u>699 W. SALISBURY PKWY, SALISBURY, MD 21801</u> For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

VEHICLE INSPECTION FORM (CONTINUED): Inventory ID #56

Repairs needed: Braking system repairs (brake calipers, hoses, pads, rotors, and master cylinder), third brake light assembly, transmission slips occasionally.