Heavy Truck Inspection Form

Inventory ID:	Asset Number: $RC-3$	Fair Market Value:
Short Description: Year 2004 Manufacturer International Model 4300 SBA LP 422		
VIN: THE MNAALG 5 H G 9 3 4 3 0 Title Restriction: DY N Mileage/Odometer: 7 4 7 4 8 4 Odometer Accurate Y DN:		
Long Description: Primary Use for Vehicle: Recycle + ruck GVW:		
This Vehicle: Starts Starts with a Boost & Is Operable Is Not Operable For Parts Only		
Date Removed From Service: 1/2074 Maintenance Records: Available \(\sqrt{\text{Not Available For Inspection}} \)		
Engine Manufacture: Gas Diesel		
This vehicle was maintained every 5 00 Days Hours Miles # of Axles Z		
Engine Condition: Is operable Needs repair Is in Unknown Condition Jake Brake: Yes No		
Engine Repairs needed:		
Transmission Manufacture: Allisca Manual Speed		
Transmission Condition is: Operable Needs Repair Unknown Rebuilt (Date:)		
Transmission Repairs Needed:		
Exterior: Color Why + C Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Low DFlat		
Damage to:		
Additional Damage to:		
Decals: ☐ None ☐ Have been sprayed ☐ Have been Removed & ☑ Impressions Remain ☐ No Impressions		
Capacity: Loader:		
Interior: Color Cloth Cloth Vinyl Leather		
Damage to Seats: Worn #Jg#5		
Damage to Dash/Floor: Dash / Pas Conched		
Radio: Brand International DAM MAM/FM DAM/FM Cassette DAM/FM CD		
Cruise Control Tilt Steering Remote Mirrors Airbags: Driver's Side Dual		
AC No AC AC Condition: Cold Wunknown Power: Windows Doorlocks Steering Seats		
Additional Equipment: Manufacturer: Model:		
Serial # Description:		
Equipment Condition: Is operable Needs repair Is in Unknown Condition		
Other Equipment:		
Location of Asset: 500 Mg/K AVE, For more information contact: 500 day Mana		