

Bus Inspection Form

Inventory ID	Asset Number <u>Trolley 270</u>	Fair Market Value:
Short Description: Year <u>2005</u> Make <u>Freightliner</u> Model <u>MB55</u>		
VIN: <u>4UZAACBm45CU68917</u> Title Restriction: ☐ Y ☒ N		
Mileage/Odometer: <u>120401</u> Odometer Accurate ☒ Y ☐ N:		
Long Description: Primary use for Bus: <u>Trolley</u> # of Passengers: <u>29</u> This vehicle: ☐ Starts ☒ Starts with a Boost and ☐ Runs ☐ Does Not Run ☐ For Parts Only Engine Manufacture: <u>Cummins</u> Engine Type: ☒ L, V ☐ Gas ☒ Diesel Engine This Vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles Engine Condition: ☐ Runs ☐ Needs repair ☒ Is in Unknown Condition Repairs needed: _____ Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available Transmission Manufacture: _____ ☒ Automatic ☐ Manual _____ Speed Transmission Condition is: ☐ Operable ☐ Needs Repair ☒ Unknown ☐ Rebuilt (Date: _____) Repairs Needed: _____ Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection		
Exterior Description: Color: <u>Blue</u> Windows: ☐ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: ☒ Low ☐ Flat _____ Damage to: _____ Additional Damage to: _____ Decals: ☐ None ☐ Have been Sprayed Over ☐ Have been removed & ☒ Impressions Remain ☐ No Impressions Other Exterior Information: _____		
Interior Description: Color <u>Brown</u> ☐ Vinyl ☐ Cloth ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: Brand _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD Air Conditioning: ☒ Yes ☐ No AC Operating Condition: ☐ Cold ☒ Unknown Other Interior Information/Options: _____		
Other Equipment: Description _____ Manufacturer _____ Model _____ Serial # _____		
Location of Asset: <u>500 Mack Ave.</u> For more information contact: <u>Jordan Mann</u>		