

Vehicle Inspection Form

Inventory ID:	Asset Number: <u>5-30</u>	Fair Market Value:																	
Short Description:																			
Year <u>2007</u>	Make <u>Pontiac</u>	Model <u>F250 XL SD</u>																	
VIN: <table border="1" style="display: inline-table; border-collapse: collapse; text-align: center;"> <tr><td>1</td><td>F</td><td>T</td><td>S</td><td>X</td><td>2</td><td>1</td><td>5</td><td>X</td><td>7</td><td>E</td><td>B</td><td>2</td><td>1</td><td>9</td><td>3</td><td>4</td></tr> </table>		1	F	T	S	X	2	1	5	X	7	E	B	2	1	9	3	4	Title Restriction: ☐ Y ☒ N
1	F	T	S	X	2	1	5	X	7	E	B	2	1	9	3	4			
Odometer: <table border="1" style="display: inline-table; border-collapse: collapse; text-align: center;"> <tr><td>7</td><td>9</td><td>0</td><td>9</td><td>4</td></tr> </table>		7	9	0	9	4	☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____												
7	9	0	9	4															
Long Description:																			
This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only																			
Engine- Type: <u>L, V</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid																			
Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition																			
Repairs needed: _____																			
This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles																			
Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection																			
Transmission: ☒ Automatic ☐ Manual <u>Speed</u> Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition																			
Repairs Needed: _____																			
Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>White</u> Windows: ☒ No Cracked Glass ☐ Cracked																			
Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: <u>Bad</u> Tread: _____ #Flat ☒ Hubcaps # _____																			
Major Damage to: _____																			
Additional Damage: <u>Dents</u>																			
Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☒ Impressions Remain ☐ No Impressions																			
Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>Gray</u> ☐ Cloth ☒ Vinyl ☐ Leather																			
Damage to Seats: <u>Torn seats</u>																			
Damage to Dash/Floor: _____																			
Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD																			
☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual																			
☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control																			
Power: ☐ Steering ☒ Windows ☒ Door Locks ☐ Seats																			
Additional Equipment: _____																			
Manufacturer _____ Model _____ Serial # _____																			
☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>500 Mack Ave</u>																			
For more information contact: <u>Jordan Mann</u>																			
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			