



Vehicle Inspection Report

Date: 9/10/2025

Asset # <u>1353</u>	VIN <u>1C6RR7KT9KS717024</u>		
Year <u>2019</u>	Make <u>Ram</u>	Model <u>1500</u>	Actual Mileage <u>129,000</u>

Task	Yes/No	Description
Starts	Yes	
Runs/Drivable	Yes	
Engine Condition: Runs / Needs Repair / Unknown Condition	Runs Good	
Windows Cracked	No	
Minor Dents/Scratches/Dings	Yes	
Major Damage	No	
Additional Damage	No	
Interior Condition	DIRTY	
Additional Equipment (plow, topper, tool box, tonneau, etc)	laptop mount	

Additional Comments

None