



Vehicle Inspection Report

Date: 9-29-25

Asset # <u>106015</u>		VIN <u>2C4RDGBG5KR521478</u>	
Year <u>2019</u>	Make <u>Dodge</u>	Model <u>Grand Caravan</u>	Actual Mileage <u>284212</u>

Task	Yes/No	Description
Starts	Yes	
Runs/Drivable	Yes	
Engine Condition: Runs / Needs Repair / Unknown Condition	Runs	
Windows Cracked	Yes	Windshield
Minor Dents/Scratches/Dings	Yes	Usual
Major Damage	No	
Additional Damage	Yes	Transmission Slipping
Interior Condition	Fair	
Additional Equipment (plow, topper, tool box, tonneau, etc)		

Additional Comments