



Vehicle Inspection Report

Date: 10/6/2025

Asset # 2590		VIN 1C3CCCAB6HN512189	
Year 2017	Make Chrysler	Model 200	Actual Mileage <u>125,903</u>

Task	Yes/No	Description
Starts	Yes	
Drivable	Yes	
Engine Condition: Runs / Needs Repair / Unknown Condition		
Windows Cracked	No	
Minor Dents/Scratches/Dings	Yes	doors, driver front quarter panel, rear bumper
Major Damage	No	
Additional Damage	No	
Interior Condition Clean / Minor Wear / Major Wear)		
Additional Equipment (plow, topper, tool box, tonneau, etc)	No	

Additional Comment Small scratches on driver's side and passenger side doors, scratch on driver's side front quarter panel, small dent on rear bumper and scratches on rear bumper.