



Vehicle Inspection Report

Date: 10/9/2025

Asset # <u>2344</u>		VIN <u>1C3CCCABXFN693973</u>	
Year <u>2015</u>	Make <u>Chrysler</u>	Model <u>200</u>	Actual Mileage <u>111,459</u>

Task	Yes/No	Description
Starts	Yes	
Drivable	Yes	
Engine Condition: Runs / Needs Repair / Unknown Condition		Runs fine
Windows Cracked	No	
Minor Dents/Scratches/Dings	Yes	
Major Damage	No	
Additional Damage	No	
Interior Condition Clean / Minor Wear / Major Wear)		Clean
Additional Equipment (plow, topper, tool box, tonneau, etc)	No	

Additional Comment