

Generic Inspection Form

Inventory ID:

ITEM#25 06699

Asset Number

06699

Anticipated Sale Price:

Short Description: 2" PUMP

Year 2020

Manufacturer HONDA

Model WB20XT3A

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☒ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☒ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # WABT-5022897

Repairs needed: NO START

Description of Use

Color _____ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____