

Generic Inspection Form

| | | |
|--|---------------------------|--|
| Inventory ID: <u>ITEM#14 96679</u> | Asset Number <u>96679</u> | Anticipated Sale Price: _____ |
| Short Description: <u>TRENCH COMPACTOR</u> | Year <u>1998</u> | Manufacturer <u>MULTIQUIP</u> Model <u>MVC 77H</u> |

Please fill in or check if apply **Long Description:**

This Equipment: Is Operable Is Not Operable For Parts Only Needs Repair The Condition is Unknown
 Hours: _____ This equipment was maintained every _____ Hours Days
Serial # HD 17449
Repairs needed: NO START, PARTS OFF - MISSING

Description of Use

Color _____ Cloth Vinyl Leather Metal Plastic Wood Rubber
Minor damage to: _____
Major damage to: _____
Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____
Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____
Serial # _____ Condition: Is Operable Needs repair Unknown Condition
Description: _____

Additional Equipment: Manufacturer _____ Model _____
Serial # _____ Condition: Is Operable Needs repair Unknown Condition
Description: _____

Additional Equipment: Manufacturer _____ Model _____
Serial # _____ Condition: Is Operable Needs repair Unknown Condition
Description: _____

Comments:

Location of Asset: _____
For more information contact: _____