

Generic Inspection Form

Inventory ID: 76680
ITEM#13

Asset Number 76680

Anticipated Sale Price: _____

Short Description: TRENCH COMPACTOR

Year 2017

Manufacturer MULTIQUIP

Model MVC-88VTHW

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☒ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☒ The Condition is Unknown

☒ Hours: 79 This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # C9924

Repairs needed: NO START, PARTS OFF

Description of Use

Color _____ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____