

Generic Inspection Form

Inventory ID:

ITEM# 24 LOT 4

Asset Number

Anticipated Sale Price:

Short Description: 2 - BLOWERS 1 - BACK PACK 1 - HAND HELD
Year 2021-22 Manufacturer STIHL Model BR700, BG86

Please fill in or check if apply

Long Description:

This Equipment: Is Operable Is Not Operable For Parts Only Needs Repair The Condition is Unknown

Hours: _____ This equipment was maintained every _____ Hours Days

Serial # 16551, 26529

Repairs needed: 1 - NO START - NO PULL 1 - NO START

Description of Use

527486088, 534055598

Color _____ Cloth Vinyl Leather Metal Plastic Wood Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____