

Vehicle Inspection Form

Inventory ID: ITEM#2 21184

Asset Number: 21184

Fair Market Value:

Short Description:

Year 2021 Make CHEVROLET Model MALIBU

VIN: 1G1ZC5ST1MFO02189

Title: Clean Title Salvage Title No Title
 Court Documents Only SF97 Form Other

Odometer: 75,491 Miles Kilometers Hours Odometer Accurate? Yes No Unknown

Long Description:

This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only

Engine- Type: 1.5 L, V 4 Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid

Engine Condition: Runs Needs repair is in unknown condition

Repairs needed:

This vehicle was maintained every _____ Days Hours Miles/Kilometers

Date Removed from Service: _____ Maintenance Records: Available Not Available For Inspection

Transmission: Automatic Manual _____ Speed Condition: Operable Needs repair Is Unknown Condition

Repairs Needed:

Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: "MUST TOW"

Exterior: Color: BURGUNDY Windows: No Cracked Glass Cracked WINDSHIELD

Minor: Dents Scratches Dings Tire Condition: GOOD Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to: RIGHT REAR, DECK LID, RIGHT TAIL LIGHT

Additional Damage: REAR BUMPER / COVER REMOVED, RIGHT REAR DOOR

Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions

Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior: Color BLACK Cloth Vinyl Leather

Damage to Seats:

Damage to Dash/Floor:

Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD

AC Condition: Cold Unknown No AC

Air Bags: Driver's Side Dual

Cruise Control Tilt Steering Remote Mirrors Climate Control

Power: Steering Windows Door Locks Seats

Additional Equipment:

Manufacturer _____ Model _____ Serial # _____

Tool Box Light Bar Ladder Rack Utility Body: Brand _____ Hitch: Type _____

Location of Asset: City of Cincinnati Fleet Services, 1106 Bates ave., Cincinnati Ohio 45225