

# Vehicle Inspection Form

Inventory ID: ITEM#9 91571

Asset Number: 91571

Fair Market Value: \_\_\_\_\_

**Short Description:**

Year 2008 Make FREIGHTLINER Model TL3 GRAPPLE TRUCK

VIN: 1FVACYDT48HZ78422 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title  
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 136,727 ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

**Long Description:**

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6.7 L, V L6 ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: \_\_\_\_\_

This vehicle was maintained every \_\_\_\_\_ ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: \_\_\_\_\_ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual \_\_\_\_\_ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: \_\_\_\_\_

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: \_\_\_\_\_

Exterior: Color: WHITE Windows: ☒ No Cracked Glass ☐ Cracked \_\_\_\_\_

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: GOOD Tread: \_\_\_\_\_ #Flat \_\_\_\_\_ Hubcaps # \_\_\_\_\_

Major Damage to: \_\_\_\_\_

Additional Damage: \_\_\_\_\_

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color GRAY ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: HOLES IN BOTH SEATS

Damage to Dash/Floor: HOLES IN DASH

Radio: ☐ Stock or ☒ Brand & Model: MP3 ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD

AC Condition: ☐ Cold ☐ Unknown ☒ No AC Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: \_\_\_\_\_

Manufacturer \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand \_\_\_\_\_ ☐ Hitch: Type \_\_\_\_\_

Location of Asset: \_\_\_\_\_