Vehicle Inspection Form

Inventory ID: 09203	Asset Number: 09203	Fair Market Value:		
Short Description:		<i>~</i>		
Year 2009 Make FORD Model FOCUS				
VIN: <u>IFAHP35N09W221862</u> Title: XClean Title Salvage Title No Title Court Documents Only SF97 Form Other				
Odometer: 103,270 Miles Kilometers Hours Odometer Accurate? Yes No Unknown				
Long Description:				
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only				
Engine- Type: ZIO L, V 4 Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid				
Engine Condition: Runs Needs repair is in unknown condition				
Repairs needed:				
This vehicle was maintained every Days Hours Miles/Kilometers				
Date Removed from Service:Maintenance Records: Available Not Available For Inspection				
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition				
Repairs Needed:				
<u>Drivetrain</u> : 2 Wheel Drive 4 Wheel Drive Condition:				
Exterior: Color: WHITE Windows: No Cracked Glass Cracked				
Minor: Dents Scratches Dings Tire Condition: Good Tread: #Flat Hubcaps #				
Major Damage to:				
Additional Damage:				
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes				
Interior: Color GRAY Cloth Vinyl Leather				
Damage to Seats:				
Damage to Dash/Floor:				
Radio: Stock or Brand & Model:AM AM/FM AM/FM Cassette AM/FM CD				
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual				
Cruise Control Tilt Steering Remote Mirrors Climate Control				
Power: Steering Windows Door Locks Seats				
	<u>—</u>			
Additional Equipment:				
Manufacturer Model Serial #				
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type				
Location of Asset:				

Vehicle Inspection Form

Inventory ID: 09200	Asset Number: 09200	Fair Market Value:		
Short Description: Year 2009 Make FORE	n Model	Focus		
VIN: IFAHP35N29W221863 Title: VClean Title Salvage Title No Title Court Documents Only SF97 Form Other				
Odometer: 92,637 Miles Kilometers Hours Odometer Accurate? Yes No Unknown				
Long Description: This Vehicle: ✓ Starts Starts with a Boost & ✓ Runs/Drivable ✓ Engine Runs Does Not Run For Parts Only Engine- Type:L, V ✓ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid				
Engine Condition: Runs Needs repair Vis in unknown condition Repairs needed: C.E.L. ON - UNDIAGNOSED				
This vehicle was maintained every Days Hours Miles/Kilometers Date Removed from Service: Maintenance Records: Available Not Available For Inspection				
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:				
Drivetrain: 2 Wheel Drive				
Exterior: Color: WHITE Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: GOOD Tread: #Flat Hubcaps #				
Major Damage to:				
Additional Damage: Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes				
Interior: Color GRAY Cloth Vinyl Leather				
Damage to Seats:				
Damage to Dash/Floor: Radio: Stock or Brand & Model: AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual				
Cruise Control Tilt Steering Remote Mirrors Climate Control Power: Steering Windows Door Locks Seats				
Additional Equipment:				
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type				
Location of Asset:				