Vehicle Inspection Form

Inventory ID: 09200	Asset Number: 09200	Fair Market Value:
Short Description: Year 2009 Make FORD Model FOCUS		
Year 2009 Make TORI		
VIN: <u>IFAHP35N29W221863</u> Title: VClean Title Salvage Title No Title Court Documents Only SF97 Form Other		
Odometer: 92,637 Miles Kilometers Hours Odometer Accurate? Yes No Unknown		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only		
Engine- Type:L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair Vis in unknown condition		
Repairs needed: <u>C.E.L. ON - UNDIAGNOSED</u> The state of t		
This vehicle was maintained every Days Hours Miles/Kilometers Date Removed from Service: Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:		
Exterior: Color: WHITE Windows: No Cracked Glass Cracked		
Minor: Dents Scratches Dings Tire Condition: GOOD Tread: #Flat Hubcaps #		
Major Damage to:		
Additional Damage:		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color GRAY Cloth Vinyl Leather		
Damage to Seats:		
Damage to Dash/Floor:		
Radio: Stock or Brand & Model: AM AM/FM AM/FM Cassette AM/FM CD		
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Model Serial #		
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset:		