## **Vehicle Inspection Form**

Inventory ID: 10201	Asset Number: 10201	Fair Market Value:
Short Description:		
Year 2010 Make FOR	0 Model	(-ocus
VIN: <u>IFAHP3FN9AW139325</u> Title: Clean Title Salvage Title No Title  Court Documents Only SF97 Form Other		
Odometer: //3,/79 Miles Kilometers Hours Odometer Accurate? Yes No Unknown		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only		
Engine- Type: 2,0 L, V 4 Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed:		
This vehicle was maintained every Days Hours Miles/Kilometers		
Date Removed from Service:Maintenance Records:AvailableNot Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:		
Exterior: Color: WHITE Windows: No Cracked Glass Cracked		
Minor: Dents Scratches Dings Tire Condition: Good Tread: #Flat Hubcaps #		
Major Damage to:		
Additional Damage:		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color GRAY Cloth Vinyl Leather		
Damage to Seats: HOLES IN DRIVERS SEAT		
Damage to Dash/Floor: Hole IN DASH		
Radio: Stock or Brand & Model: AM AM/FM AM/FM Cassette AM/FM CD		
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Model Serial #		
Tool Box Light Bar Ladder Rack Utility Body: BrandHitch: Type		
Location of Asset:		