Vehicle Inspection Form

Inventory ID: 90673 Asset Number: 90673 Fair Market Value:
Short Description:
Year 2019 Make KIA Model CADENZA
VIN: KNALC4J15K51712 04 Title: Clean Title Salvage Title No Title Court Documents Only SF97 Form Other
Odometer: 42,360 Miles Kilometers Hours Odometer Accurate? Yes No Unknown
Long Description:
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only
Engine-Type: 3.3 L, V 6
Engine Condition: Kuns Needs repair is in unknown condition
Repairs needed:
This vehicle was maintained every Days Hours Miles/Kilometers
Date Removed from Service: Maintenance Records: Available Not Available For Inspection
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition
Repairs Needed:
Drivetrain: 2 Wheel Drive Condition:
Exterior: Color: Blue Windows: No Cracked Glass Cracked
Minor: Dents Scratches Dings Tire Condition: Good Tread: #Flat Hubcaps #
Major Damage to:
Additional Damage: RIGHT SIDE MIRROIZ LOSSE, FRONT BUMPON COVER TIR M CRACKED
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions
Emergency equip: None Has been removed & There are holes in the exterior There are no holes
Interior: Color BLACK Cloth Vinyl Leather
Damage to Seats:
Damage to Dash/Floor:
Radio: Stock or Brand & Model:AM/FM DAM/FM Cassette AM/FM CD
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual
Cruise Control Tilt Steering Remote Mirrors Climate Control
Power: Steering Windows Door Locks Seats
Additional Equipment:
Manufacturer Model Serial #
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type
Location of Asset: City of Cincinnati Fleet Services , 1106 Bates ave., Cincinnati Ohio 45225