

Vehicle Inspection Form

Inventory ID: <u>ITEM # 2 90859</u>	Asset Number: <u>90859</u>	Fair Market Value:
Short Description: Year <u>2009</u> Make <u>FORD</u> Model <u>F250 4X4</u>		
VIN: <u>1FTNF21589EA60070</u>	Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only ☐ SF97 Form ☐ Other	
Odometer: <u>126,903</u> ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown		

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 5.4 L, V 8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: _____

This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____

Exterior: Color: WHITE Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: GOOD Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to: LEFT SIDE OF BED

Additional Damage: LEFT DOOR / RUNNING BOARD

Decals: ☒ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior: Color GRAY ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: HOLE IN SEAT

Damage to Dash/Floor: HOLES IN DASH AND FLOOR

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: TRUCK CRAFT ALUMINUM BED INSERT

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____