

# Generic Inspection Form

Inventory ID:

ITEM #11 92812

Asset Number

92812

Anticipated Sale Price:

Short Description:

KUBOTA UTILITY VEHICLE AWD (DIESEL)

Year

Manufacturer

KUBOTA

Model

RTV900W6HA

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☒ Hours: 2379 This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days

Serial # KRTV900A910A0307

Repairs needed: \_\_\_\_\_

Description of Use

Color \_\_\_\_\_ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Width/Depth: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment:

Manufacturer

Model

Serial #

Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment:

Manufacturer

Model

Serial #

Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment:

Manufacturer

Model

Serial #

Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_