

Generic Inspection Form

Inventory ID:

~~ITEM #~~ 11881

Asset Number

11881

Anticipated Sale Price:

Short Description: AIRPORT SNOW BROOM TRUCK

Year 1991

Manufacturer OSHKOSH

Model HB-251B-MP3

Please fill in or check if apply

Long Description: 13096M, 2762HR, 2029HR

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 10T3E1BX5N1046192

Repairs needed: OIL LEAKS, HYDRAULIC LEAKS

Description of Use

Color _____ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____