

Vehicle Inspection Form

Inventory ID: <u>ITEM#5 60664</u>	Asset Number: <u>60664</u>	Fair Market Value:
Short Description: Year <u>2016</u> Make <u>CHEVROLET</u> Model <u>COLORADO 4DR, 4WD</u>		
VIN: <u>1GCHTB38G1322804</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other		
Odometer: <u>124,910</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 3.6 L, V 6 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: _____

This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____

Exterior: Color: WHITE Windows: ☒ No Cracked Glass ☐ Cracked _____

Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: GOOD Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to: _____

Additional Damage: _____

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior: Color GRAY ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: _____

Damage to Dash/Floor: HOLES IN DASH AND FLOOR

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☒ Cold ☐ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment: ROOF AMBER 360° LIGHT, BED CAP

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____