

Bus Inspection Form

Inventory ID 6090-8096	Asset Number 485466	Fair Market Value: \$3500.00
Short Description:		
Year <u>2009</u>	Make <u>BLUEBIRD</u>	Model <u>ACTIVITY BUS</u>
VIN: <u>1BAKGCKAX9F259756</u>		
Mileage/Odometer: <u>58530</u>		
Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> No Title <input type="checkbox"/> Other		
Mileage/Odometer: <u>58530</u> <input checked="" type="checkbox"/> Mi <input type="checkbox"/> Km <input type="checkbox"/> Hrs Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
Long Description:		
Primary use for Bus: <u>ACTIVITY BUS</u>		# of Passengers: <u>72</u>
This vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only		
Engine Manufacture: <u>CATERPILLAR</u>		Engine Type: <u>C-7</u> L, V <u>IL-6</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine
This Vehicle was maintained every <u>5,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles		
Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Repairs needed: _____		
Date Removed From Service: <u>9-29-2025</u>		Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available
Transmission Manufacture: <u>ALLISON</u>		<input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u> </u> Speed
Transmission Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown Rebuilt (Date: <u> </u>)		
Repairs Needed: _____		
Date Removed From Service: _____		Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection
Exterior Description:		
Color: <u>YELLOW</u>		Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____
Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings		Tire Condition: Low <u> </u> Flat <u> </u>
Damage to: <u>TIRES FAIR CONDITION</u>		
Additional Damage to: _____		
Decals: <input type="checkbox"/> None <input checked="" type="checkbox"/> Have been Sprayed Over <input type="checkbox"/> Have been removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions		
Other Exterior Information: _____		
Interior Description:		
Color <u>BLUE&GREY</u> <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Cloth <input type="checkbox"/> Leather		
Damage to Seats: <u>GOOD</u>		
Damage to Dash/Floor: <u>GOOD</u>		
Radio: Brand _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD		
Air Conditioning: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No AC Operating Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown		
Other Interior Information/Options: _____		
Other Equipment: Description _____		
Manufacturer _____ Model _____ Serial # _____		
Location of Asset: <u>3319 GOLDMINE RD. MONROE, NC 28110 KEITH DOCKERY CELL: 704-516-7237</u>		