

Bus Inspection Form

Inventory ID <u>1023</u>	Asset Number <u>820740</u>	Fair Market Value: _____
--------------------------	----------------------------	--------------------------

Short Description:
 Year 2014 Make International Model IC Navistar

VIN:

4	D	R	B	U	S	K	L	4	E	B	4	8	8	1	8	2
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

 Title Restriction: Y N

Mileage/Odometer:

1	1	3	1	5	5
---	---	---	---	---	---

 Odometer Accurate Y N: _____

Long Description:

Primary use for Bus: _____ # of Passengers: 42

This vehicle: Starts Starts with a Boost and Runs Does Not Run For Parts Only
 Engine Manufacture: Max Force Engine Type: L, V 8 Gas Diesel Engine

This Vehicle was maintained every 5,000 Days Hours Miles

Engine Condition: Runs Needs repair Is in Unknown Condition

Repairs needed: N/A

Date Removed From Service: 3-3-2021 Maintenance Records: Available Not Available

Transmission Manufacture: Allison Automatic Manual Speed _____

Transmission Condition is: Operable Needs Repair Unknown Rebuilt (Date: _____)

Repairs Needed: N/A

Date Removed From Service: 3-3-2021 Maintenance Records: Available Not Available For Inspection

Exterior Description:

Color: Yellow Windows: No Cracked Glass Cracked _____

Minor: Dents Scratches Dings Tire Condition: Low Flat Poor

Damage to: N

Additional Damage to: _____

Decals: None Have been Sprayed Over Have been removed & Impressions Remain No Impressions

Other Exterior Information: _____

Interior Description:

Color Blue Vinyl Cloth Leather

Damage to Seats: _____

Damage to Dash/Floor: _____

Radio: Brand _____ AM AM/FM AM/FM Cassette AM/FM CD

Air Conditioning: Yes No AC Operating Condition: Cold Unknown

Other Interior Information/Options: _____

Other Equipment: Description Wheel chair lift

Manufacturer Braun Model _____ Serial # _____

Location of Asset: _____

For more information contact: _____