

## Vehicle Online Form

<b>Inventory ID:</b>	<b>Bid Increment:</b>	<b>Opening Bid :</b>	<b>Reserve:</b>																	
<b>Short Description:</b> Year <u>2016</u> Make <u>Chevrolet</u> Model <u>Silverado 2500hd</u>																				
<b>VIN:</b> <table border="1" style="display: inline-table; border-collapse: collapse; text-align: center;"> <tr> <td>1</td><td>G</td><td>C</td><td>2</td><td>K</td><td>U</td><td>E</td><td>G</td><td>4</td><td>G</td><td>Z</td><td>1</td><td>7</td><td>3</td><td>4</td><td>1</td><td>4</td> </tr> </table> Title Restriction: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N				1	G	C	2	K	U	E	G	4	G	Z	1	7	3	4	1	4
1	G	C	2	K	U	E	G	4	G	Z	1	7	3	4	1	4				
<b>Mileage/Odometer:</b> <table border="1" style="display: inline-table; border-collapse: collapse; text-align: center;"> <tr> <td>1</td><td>0</td><td>0</td><td>8</td><td>3</td><td>9</td> </tr> </table> Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____				1	0	0	8	3	9											
1	0	0	8	3	9															
<b>Long Description:</b> <b>Body Style:</b> <input type="checkbox"/> 2-door <input checked="" type="checkbox"/> 4-door <input checked="" type="checkbox"/> Short bed <input type="checkbox"/> Long bed																				
This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only																				
<b>Engine- Type:</b> <u>6.0 L, V 8</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine																				
Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition																				
Repairs needed: _____																				
This vehicle was maintained every <u>3,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles																				
<b>Date Removed From Service:</b> <u>6-6-2025</u> <b>Maintenance Records:</b> <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection																				
<b>Transmission:</b> <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u>    </u> Speed																				
Transmission Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition																				
Repairs Needed: _____																				
<b>Drivetrain:</b> <input type="checkbox"/> 2 Wheel Drive <input checked="" type="checkbox"/> 4 Wheel Drive      Condition: <u>    </u> Operable																				
<b>Exterior:</b> Color: <u>Red</u> <b>Windows:</b> <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____																				
Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings <b>Tire Condition:</b> <input type="checkbox"/> Low <u>    </u> <input type="checkbox"/> Flat <u>    </u> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4																				
Does the vehicle have: <input type="checkbox"/> Hail damage <input checked="" type="checkbox"/> Rust																				
Major Damage to: <u>Wheel Arches Rotten All 4 Corners..... Drivers Side Floor Rotten</u>																				
Additional Damage: _____																				
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed <u>or</u> <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions																				
Emergency equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed & <input checked="" type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes																				
<b>Interior:</b> Color <u>Grey</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather																				
Damage to Seats: <u>Drivers Seat Worn</u>																				
Damage to Dash/Floor: <u>Holes in dash from after market equipment removal..... rot in drivers floor pan</u>																				
Radio: <input type="checkbox"/> Stock <u>or</u> <input checked="" type="checkbox"/> Brand & Model: <u>Sony</u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD																				
<input checked="" type="checkbox"/> AC (Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown) <input type="checkbox"/> No AC      Air Bags <input type="checkbox"/> drivers side <input checked="" type="checkbox"/> dual																				
<input type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input checked="" type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control																				
Power: <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats																				
<b>Additional Equipment:</b> <u>8 ft fisher plow - full size light bar - both in operable condition</u>																				
<b>Location of Asset:</b> <u>201 Run Hill rd Brewster Ma 02631</u>																				
<b>For more information contact:</b> _____																				