



7127 S Lindbergh Blvd St Louis
MO US 63125
<https://www.southcountyautos.com/>

Customer

MO DEPT OF NATURAL
RESOURCES BRYTANIE
+1 - (314) 416 - 2068
Kimberly.tat@dnr.mo.gov

Vehicle

2016 Chrysler 200
VIN
1C3CCCFB7GN183459
LX: Car 2.4L I4 4DR
Naturally Aspirated Gas
Fi: FWD: AT: Car
69,013 Mi In

RO# : 649219

Tag# : 2288

Technician
805

Multi-Point Inspection

2. MPVI

✓ Pass: 49

⚠ Caution: 2

✗ Fail

⊘ Not Applicable

ℹ Refer Notes

Tires

Tread Depth

| | |
|-------------|--------------|
| Left Front | 9 /32" ✓ ⚠ ⊘ |
| Right Front | 9 /32" ✓ ⚠ ⊘ |
| Left Rear | 9 /32" ✓ ⚠ ⊘ |
| Right Rear | 9 /32" ✓ ⚠ ⊘ |

Tire Pressure, Condition & Age

| | |
|---------------------------|--------------|
| Left Front Tire Pressure | 36 PSI ✓ ⚠ ⊘ |
| Right Front Tire Pressure | 36 PSI ✓ ⚠ ⊘ |
| Left rear Tire Pressure | 36 PSI ✓ ⚠ ⊘ |
| Right Rear Tire Pressure | 36 PSI ✓ ⚠ ⊘ |
| Alignment needed | ✓ ⊘ |
| Balance needed | ✓ ⊘ |
| Rotation needed | ✓ ⊘ |

Brakes

Brake System

Brake System (Including Lines, Hoses and Parking Brake) ✓ ⚠ ⊘

Brake Pads

| | |
|-------------|------------|
| Left front | 7 MM ✓ ⚠ ⊘ |
| Right front | 7 MM ✓ ⚠ ⊘ |
| Left rear | 7 MM ✓ ⚠ ⊘ |
| Right rear | 7 MM ✓ ⚠ ⊘ |

Interior & Exterior

Lights

| | |
|--|-------|
| Headlights/Turn Signals/High Beams/Fog Lights | ✓ ⚠ ⊘ |
| Tail Lights/Turn Signals/Brake Lights/Reverse Lights | ✓ ⚠ ⊘ |
| Exterior Lamps/Hazard Lights | ✓ ⚠ ⊘ |

Wipers & Horn

| | |
|--------------|-------|
| Front Wipers | ✓ ⚠ ⊘ |
| Rear Wiper | ✓ ⚠ ⊘ |

Interior & Exterior

Wipers & Horn

Horn ✓ ⚠ ⊘

Other Services

Safety belt reminder lights ✓ ⚠ ⊘

Under Hood

Fluid Levels

| | |
|---|------------|
| Engine Oil Level | Full ✓ ⚠ ⊘ |
| Coolant | Full ✓ ⚠ ⊘ |
| Power Steering Fluid | ✓ ⚠ ⊘ |
| Brake Reservoir Fluid | ✓ ⚠ ⊘ |
| Windshield Washer Fluid | ✓ ⚠ ⊘ |
| Transmission Fluid | ✓ ⚠ ⊘ |
| Diesel Exhaust Fluid (DEF) | ✓ ⚠ ⊘ |
| Drive axle | ✓ ⚠ ⊘ |
| Transfer case | ✓ ⚠ ⊘ |
| Reset Oil Life Monitor | ✓ ⚠ ⊘ |
| Filters & Cooling Systems | |
| Passenger Compartment Air Filter | ✓ ⚠ ⊘ |
| Engine Air Filter | ✓ ⚠ ⊘ |
| Belts/Hoses/Spark Plugs | |
| Belts: Engine, Accessory, Serpentine and/or V-drive | ✓ ⚠ ⊘ |
| Cooling System Hoses | ✓ ⚠ ⊘ |
| Heater/AC Hoses/Hydraulic Hoses and Connections | ✓ ⚠ ⊘ |
| Spark Plugs | ✓ ⚠ ⊘ |
| Battery | |
| Battery Condition | ✓ ⚠ ⊘ |
| Battery, Cables and Connections | ✓ ⚠ ⊘ |



Customer
MO DEPT OF NATURAL
RESOURCES BRYTANIE
+1 - (314) 416 - 2068








































Vehicle
2016 Chrysler 200
VIN
1C3CCCFB7GN183459

RO# : 649219
Tag# : 2288
Technician
805




7127 S Lindbergh Blvd St Louis
MO US 63125
[https://www.southcountyautos.co
m/](https://www.southcountyautos.com/)

Multi-Point Inspection

Under Vehicle

| | |
|--|---|
| Steering/Suspension | |
| Steering Components |     |
| Front Suspension Components |     |
| Rear Suspension Components |     |
| Transmission/Axle | |
| CV Drive Axle Boots or Driveshafts & U-joints |     |
| Check For Fluid Leaks | |
| Engine Oil Leaks |     |
| Cooling System Leaks |     |
| Brake System Leaks |     |
| Transmission System Leaks |     |
| Steering System Leaks |     |
| Other Services | |
| Visual Inspection of Exhaust system components |    |

Pending Recommendation(s)

| | | | | |
|---|---------------------|---------------------------------------|--------------|------------|
|  | 1. REC | wire harness | Customer Pay | \$1,829.70 |
| | Parts | | | \$1,569.75 |
| | Name | Quantity | Unit Price | Sale Price |
| | 68395045AA - WIRING | 1 | \$1,569.75 | \$1,569.75 |
| | Labor | | | \$259.95 |
| | Fee | | | \$0.00 |
|  | 2. BFX | PERFORM BRAKE FLUID EXCHANGE-MPC06012 | Customer Pay | \$186.94 |
|  | 3. FUELIND | FUEL/AIR INDUCTION CLEANING | Customer Pay | \$239.67 |



7127 S Lindbergh Blvd St Louis
MO US 63125
[https://www.southcountyautos.co
m/](https://www.southcountyautos.com/)

Customer
MO DEPT OF NATURAL
RESOURCES BRYTANIE
+1 - (314) 416 - 2068

Vehicle
2016 Chrysler 200
VIN
1C3CCCFB7GN183459

RO# : 649219
Tag# : 2288
Technician
805

Pending Recommendation(s)



4. THRTBDY THROTTLE BODY SERVICE

Customer Pay \$189.33

Additional Fees \$0.00

Tax \$121.47

Recommendations Estimate \$2,567.11