

Vehicle Inspection Form

Inventory ID: PD-2025-0008	Asset Number: 421	Fair Market Value:																	
Short Description: Year <u>2003</u> Make <u>BUICK</u> Model <u>CENTURY</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 200px;"> <tr> <td>2</td><td>G</td><td>4</td><td>W</td><td>S</td><td>5</td><td>2</td><td>J</td><td>4</td><td>3</td><td>1</td><td>2</td><td>7</td><td>4</td><td>2</td><td>3</td><td>3</td> </tr> </table> Title Restriction: ☒ Y ☐ N			2	G	4	W	S	5	2	J	4	3	1	2	7	4	2	3	3
2	G	4	W	S	5	2	J	4	3	1	2	7	4	2	3	3			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr> <td> </td><td> </td><td> </td><td> </td><td> </td><td> </td> </tr> </table> ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: <u>UNKNOWN</u>																			
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>3.1</u> L, V <u>6</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>UNKNOWN</u> This vehicle was maintained every <u>UNKNOWN</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>UNKNOWN</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u> </u> Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>UNKNOWN</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>UNKNOWN</u>																			
Exterior: Color: <u>TAN</u> Windows: ☒ No Cracked Glass ☐ Cracked <u> </u> Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>4x GOOD</u> Tread: <u> </u> #Flat <u> </u> Hubcaps # <u> </u> Major Damage to: <u>UNKNOWN</u> Additional Damage: <u>UNKNOWN</u> Decals: ☒ None ☐ Have Been Sprayed <u>or</u> ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>TAN</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>NONE</u> Damage to Dash/Floor: <u>NONE</u> Radio: ☒ Stock <u>or</u> ☐ Brand & Model: <u> </u> ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☐ Cold ☒ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats																			
Additional Equipment: <u>NONE</u> Manufacturer <u> </u> Model <u> </u> Serial # <u> </u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand <u> </u> ☐ Hitch: Type <u> </u>																			
Location of Asset: <u>780 BRACEVILLE ROBINSON ROAD NEWTON FALLS OHIO 44444</u> For more information contact: <u> </u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			