

WORK ORDER: 231601					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	06/09/2010	
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP			Date Out:	06/11/2010	
UNIT NUMBER INFORMATION					
YEAR: 2010		ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 1			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST
PENDERGRAFT	06/10/2010	General Repair / Body / Decals / Install		1.20	\$78.039
PENDERGRAFT	06/15/2010	General Repair / Body / Markings / Remove&Replace		0.78	\$50.389
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
CITY	NS	2.000	\$1.540	06/10/2010	\$3.850
PART NAME: DECAL "CITY SEAL"		REPAIR: General Repair / Unit Services / Complete Unit / Part Issue			
WORK ORDER TOTALS					
TOTAL PARTS:	\$3.850	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000	
TOTAL LABOR:	\$128.428	TOTAL MISC:		\$0.000	TOTAL COST: \$132.278
NOTES					
231601 -					
INSTALL CITY SEALS AND NUMBERS-					
CALL TY WHEN READY- TT					
seals and numbers installed					
06/10/2010 @ 15:15:43					
Saftey Triangle installed					
06/15/2010 @ 11:02:03					

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 239011				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	10/25/2010
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	10/25/2010
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 35	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
CRITTENDEN	10/25/2010	Vandalism / Tire / Tube / Tire Industrial / Damaged tire	1.20	\$48.000
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$48.000	TOTAL MISC:	\$0.000	TOTAL COST: \$48.000
NOTES				
239011 -				
VANDALS SLASHED TIRE ATHLETIC PARK AT 5812 BUFFALOE RD BEHIND FIRE STATION				
FRT TIRE SIZE 10.00/16 SL JOA				
DOUG EMORY 278-6249				
10/25/2010 @ 11:17:40 - repaired tube and tier on rf 2 patches 3 holes				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 245488					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	03/16/2011	
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP			Date Out:	03/25/2011	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 41		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
PRICE	03/23/2011	General Repair / Unit Services / Complete Unit / Inspect	5.44	\$353.690	
PRICE	03/24/2011	General Repair / Light System / Light Exterior / Install	6.92	\$449.824	
PRICE	03/25/2011	General Repair / Cab / Headliner Roof / Repair	2.96	\$192.129	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
3520W-88	NS	4.000	\$50.870	03/23/2011	\$254.352
PART NAME: STROBE LIGHT		REPAIR: General Repair / Light System / Light Exterior / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$254.352	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$995.643	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,249.995
NOTES					
245488 -					
HANDLE FOR THE HOOD WAS NOT INSTALLED-					
HYD GAUGE IS NOT WORKING-					
INSTALL LED LIGHT ON TOP- EARL WILL LET US KNOW WHAT COLOR-					
CONTACT EARL DAVIS/ 278-6261 TT					
03/24/2011 @ 07:44:37 LOOKED FOR HOOD RELEASE LATCH TOOL. COULD NOT FIND IT HOWEVER THE TOOL IS ONLY A ROD THAT ONE WOULD STICK THOUGHT THE HOLE IN THE GRILL AND PRESS THE LATCH TO RELEASE AND A NO. 2 SCREW DRIVER WORKS GREAT. REMOVED HEAD LINER TO GAIN ACCESS FOR RUNNING CORNER STROBES. MADE TWO FRONT BRACKETS AND TWO REAR BRACKETS FOR WARNING LIGHTS. INSTALLED STROBES . HYD GAUGE IS ONLY A RESTRICTION GAUGE AND DOES NOT MOVE UNTIL THE HYD FILTER BEGINS TO STOP UP. IT IS OK. (WP)					

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 246426				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	04/05/2011
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP			Date Out:	04/05/2011
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 41	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
HANSEN	04/05/2011	Road Call / Cooling Engine / System / Diagnosis	0.17	\$10.830
HANSEN	04/05/2011	Road Call / Cooling Engine / Clamp Hose / Repair	0.91	\$59.189
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$70.019	TOTAL MISC:	\$0.000	TOTAL COST: \$70.019
NOTES				
246426 -				
Driver complaint of engine overheating				
Contact Earl @ 278-6261				
found a loose hose clamp and loose hose				
replaced clamp and refilled with coolant already charged out.				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 249059				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	05/26/2011
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP			Date Out:	06/30/2011
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 88	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	<b>TOTAL COST: \$0.000</b>
NOTES				
249059 -				
A/C NOT COOLING-				
UNDER WARRANTY! EXPIRES 6/7/11				
CONTACT DAVID MORTON/ 524-7594 TT				
05/26/2011 @ 13:41:42- CUSTOMER TRANSPORTED TO SENTER TRACTOR FOR REPAIR-				
NOTE: THIS NEW TRACTOR HAS BEEN HARDLY USED AND WARRANTY IS ABOUT TO EXPIRE. HAS NOT ACCUMULATED ENOUGH HOURS TO DO A SERVICE.				
06/02/2011 @ 08:32:53 Called David Morton to inform him tractor warranty was completed by Senter Tractor. Waiting for repair information from Senter. RU				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 249926				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	06/14/2011
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP			Date Out:	06/28/2011
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 97	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	<b>TOTAL COST: \$0.000</b>
NOTES				
249926 -				
A/C WENT OUT AGAIN-				
JUST GOT IT BACK FROM SENTER TRACTOR-				
UNDER WARRANTY!				
CONTACT EARL DAVIS/ 278-6261 TT				
<a href="#">06/14/2011 @ 13:55:50-EARL DAVIS IS TAKING TRACTOR BACK TO SENTER</a>				
<a href="#">06/16/2011 @ 12:36:38 Tractor ready at Senter.</a>				
<a href="#">Warranty repair of A/C, found another line loose, cleaned, resealed line, evacuated system amd recharged. Checked operation .. OK. RU</a>				

WORK ORDER: 255986				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	09/30/2011
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP			Date Out:	10/07/2011
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

CLASS: Farm Tractor

METERS: Hour Meter - 182

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
HANSEN	10/04/2011	Preventive Maintenance Service / Preventative Maintenance / PM B Service / Perform	0.76	\$49.449
GAY	10/06/2011	Preventive Maintenance Service / Preventative Maintenance / PM B Service / Perform	2.48	\$161.468

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
87356351	NS	1.000	\$55.490	10/06/2011	\$69.363
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
87356353	NS	1.000	\$55.300	10/06/2011	\$69.125
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
84171722	NS	1.000	\$23.170	10/06/2011	\$28.963
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
CK4T	S	11.000	\$1.595	10/06/2011	\$21.934
PART NAME: ENGINE OIL, BULK, 15W40		REPAIR: General Repair / Lubrication / Fluid Auto Lube / Fill Fluids			
87329736	NS	1.000	\$7.410	10/06/2011	\$9.263
PART NAME: FUEL FILTER		REPAIR: General Repair / Lubrication / Misc Parts / Remove&Replace			
84228488	NS	1.000	\$22.490	10/06/2011	\$28.113
PART NAME: OIL FILTER		REPAIR: General Repair / Lubrication / Misc Parts / Remove&Replace			

WORK ORDER TOTALS					
TOTAL PARTS:	\$226.761	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$210.917	TOTAL MISC:	\$0.000	TOTAL COST:	\$437.678

NOTES
255986 -
NEVER BEEN SERVICED-
PMB
RUSH IF POSSIBLE
CONTACT EARL DAVIS/ 278-6261 TT
dana ordered filters
10/06/2011 @ 08:09:30- FILTERS ARE HERE!
I DID THE SERVICE.

WORK ORDER: 260669			
UNIT NUMBER: 402360			
Work Order Status: C - C - CLOSED		Date In:	01/06/2012
Work Order Shop: F21 - F21 FLEET NB HEAVY EQUIPMENT SHOP		Date Out:	01/18/2012

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

UNIT NUMBER INFORMATION					
YEAR: 2010		ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: ZZ100 6221 704010 509    PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 273			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST
ZRILEY	01/17/2012	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		11.26	\$732.093
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
33002	NS	1.000	\$1.240	01/17/2012	\$1.550
PART NAME: FUEL FILTER		REPAIR:    General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
57794	NS	1.000	\$11.240	01/17/2012	\$14.050
PART NAME: HYD FILTER    2314 NEW HOLLAND TN65D		REPAIR:    General Repair / Hydraulic System / Filter Hydraulics / Remove&Replace			
CK4T	S	12.000	\$1.595	01/17/2012	\$23.928
PART NAME: ENGINE OIL, BULK, 15W40		REPAIR:    General Repair / Lubrication / Fluid Auto Lube / Fill Fluids			
5196842	NS	2.000	\$34.510	01/13/2012	\$86.276
PART NAME: CAB FILTER		REPAIR:    General Repair / Air Supply / Misc Parts / Remove&Replace			
84228488	NS	1.000	\$22.490	01/13/2012	\$28.113
PART NAME: OIL FILTER		REPAIR:    General Repair / Lubrication / Misc Parts / Remove&Replace			
5194879	NS	1.000	\$30.590	01/13/2012	\$38.238
PART NAME: HYDRAULIC FILTER		REPAIR:    General Repair / Lubrication / Misc Parts / Remove&Replace			
87356353	NS	1.000	\$55.300	01/13/2012	\$69.125
PART NAME: AIR FILTER		REPAIR:    General Repair / Lubrication / Misc Parts / Remove&Replace			
87356351	NS	1.000	\$55.490	01/13/2012	\$69.363
PART NAME: AIR FILTER		REPAIR:    General Repair / Lubrication / Misc Parts / Remove&Replace			
84171722	NS	1.000	\$23.170	01/13/2012	\$28.963
PART NAME: FUEL FILTER		REPAIR:    General Repair / Lubrication / Misc Parts / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$359.606	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$732.093	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,091.699
NOTES					



W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

260669 -
Perform PM-C. RU
Attached WO# 308885 for Mower.
Contact Earl Davis @ 278-6261
Drained/Filled the engine oil, Removed/Replaced the oil filter:
Removed/Replaced the primary and inner fuel filter:
Removed/Replaced the hydraulic filter: Note, had to remove part of the engine frame in order to remove the hydraulic filter: hyd oil looked very clean- did not replace.
Greased entirely:
Radiator and condenser had to be cleaned free of debris :
checked and filled all fluids:
Removed/Replaced both cab filters:
Inspected belts and checked alternator out put ok:
Checked all lights and horn OK:
Inspected the undercarriage OK:
Inspected steering assembly and tires OK:
Removed/Replaced the hydraulic screen filter:
Checked the wiper blades OK:

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 268816					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	06/22/2012	
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	06/22/2012	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 349		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
CRITTENDEN	06/22/2012	Road Call / Tire / Tube / Tire Industrial / Damaged tire	1.60	\$64.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
1000x16T	NS	1.000	\$21.390	06/22/2012	\$26.738
PART NAME: TUBE-tractor front		REPAIR: Road Call / Tire / Tube / Tire Industrial / Damaged tire			
1000X16N	NS	1.000	\$190.895	06/22/2012	\$238.619
PART NAME: NEW TIRE		REPAIR: Road Call / Tire / Tube / Tire Industrial / Damaged tire			
WORK ORDER TOTALS					
TOTAL PARTS:	\$265.357	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$64.000	TOTAL MISC:	\$0.000	TOTAL COST:	\$329.357
NOTES					
268816 -					
L/FRT. TIRE FLAT -HIT A MAN HOLE @ 00 SUMMIT & WATER WORKS					
524-7594 DAVID ESP 1000x16 tire size F2 near old water plant off S. Wilmington st					
06/22/2012 @ 12:35:02 - damaged tire , damaged tube, installed 1 new tire and 1 new tube on lf					
WORK ORDER: 268968					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	06/26/2012	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	07/06/2012	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509    PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 349

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
SQUIRES	06/27/2012	General Repair / Blade / System / Diagnosis	0.69	\$37.950
SQUIRES	06/28/2012	Add On / Hydraulic System / Hose Hydraulic / Remove&Replace	3.22	\$176.949
AVILA	07/06/2012	Add On / Hydraulic System / Hose Hydraulic / Remove&Replace	1.69	\$110.139

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
UTF	S	3.000	\$40.087	07/06/2012	\$150.327
PART NAME: UNIVERSAL TRACTOR FLUID		REPAIR: General Repair / Hydraulic System / Fluid Hydraulic / Fill Fluids			
UTF	S	1.000	\$40.087	07/06/2012	\$50.109
PART NAME: UNIVERSAL TRACTOR FLUID		REPAIR: General Repair / Hydraulic System / Fluid Hydraulic / Fill Fluids			
UTF	S	1.000	\$40.087	07/06/2012	\$50.109
PART NAME: UNIVERSAL TRACTOR FLUID		REPAIR: General Repair / Hydraulic System / Fluid Hydraulic / Fill Fluids			
7216-1502	NS	1.000	\$12.240	06/29/2012	\$15.300
PART NAME: HYD RETURN LINE 1 1/2"		REPAIR: General Repair / Hydraulic System / Hose Hydraulic / Remove&Replace			
87312357	NS	1.000	\$12.100	07/02/2012	\$15.125
PART NAME: KEY		REPAIR: General Repair / Ignition System / Misc Parts / Remove&Replace			

WORK ORDER TOTALS				
TOTAL PARTS:	\$280.970	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$325.038	TOTAL MISC:	\$0.000	<b>TOTAL COST: \$606.008</b>

NOTES
268968 -  REPLACE HYDRAULIC HOSE ON THE PTO PUMP  Installed new suction hose. Added 25 gallons of UTF-5 FUIILD.  524-7594  DAVID  Repairs on tractor complete. 105/311  Replace bent door key

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 271553					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	08/15/2012	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	08/21/2012	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 406		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
AVILA	08/20/2012	General Repair / Electrical Aux / System / Diagnosis	1.87	\$121.618	
AVILA	08/21/2012	Add On / PTO / Switch PTO / Remove&Replace	0.98	\$63.829	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
87311254	NS	1.000	\$79.490	08/21/2012	\$99.363
PART NAME: SWITCH ASSY PTO		REPAIR: General Repair / PTO / Switch PTO / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$99.363	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$185.447	TOTAL MISC:	\$0.000	TOTAL COST:	\$284.810
NOTES					
271553 -					
REAR MOWING DECK INOP. (CK. PTO SWITCH) ESP					
Checked switch- not holding PTO on. Visually inspected transmission and topped off fluid: in-shop supply. When holding switch manually, PTO stays on. Seems like internal switch fault, causing concern. Switch on order. Replaced switch and test. PTO working as designed.					
Repair complete. 105					
08/21/2012 @ 13:06:56					
524-7594					
ORDERED PTO SWITCH 8-20 ETA 8-21 EK					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 272535					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	08/31/2012	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	09/04/2012	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 431		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
AVILA	09/04/2012	General Repair / Driveability / System / Diagnosis	2.31	\$149.990	
AVILA	09/04/2012	General Repair / Air Intake Engine / Filter Air / Remove&Replace	0.72	\$47.050	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
87037984	NS	1.000	\$64.100	09/04/2012	\$80.125
PART NAME: FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$80.125	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$197.040	TOTAL MISC:	\$0.000	TOTAL COST:	\$277.165
NOTES					
272535 -  Triangle/diamond shape service light on in dash  needs air filter replaced albj  call Earl Davis when ready 278-6261  Test drove tractor- no warning lights on at this time. Checked air filter- very dirty. Front of radiator area also very dirty. Pressure washed tractor. Blew out condensor, intercooler, oil cooler and radiator. Replaced air filter. Test drove tractor again, still no faults found. Parked in old SWS lot. 105  09/04/2012 @ 10:15:02					
WORK ORDER: 276624					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	11/21/2012	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	11/29/2012	
UNIT NUMBER INFORMATION					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509    PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 476

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
AVILA	11/26/2012	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	2.18	\$141.718
AVILA	11/26/2012	Add On / Cranking System / Battery / Remove&Replace	1.13	\$73.760
AVILA	11/27/2012	Add On / Light Emergency / Light Strobe / Remove&Replace	3.24	\$210.349
AVILA	11/27/2012	Add On / Light System / Bulb / Remove&Replace	1.20	\$78.219
CRITTENDEN	11/27/2012	General Repair / Tire / Tube / System / Inspect	0.30	\$12.000
AVILA	11/29/2012	General Repair / Glass-Component / Mirror / Diagnosis	1.20	\$77.840
AVILA	11/29/2012	Add On / Light System / Light Exterior / Remove&Replace	0.52	\$33.850

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
84228488	NS	1.000	\$24.990	11/26/2012	\$31.238
PART NAME: OIL FILTER 57488		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
5199761	NS	1.000	\$57.490	11/29/2012	\$71.863
PART NAME: LAMP		REPAIR: Add On / Light Emergency / Light Strobe / Remove&Replace			
CJ4G	NS	3.000	\$9.290	11/26/2012	\$34.839
PART NAME: ENGINE OIL 15W40 GAL CLOSED.		REPAIR: General Repair / Engine Block / System / Part Issue			
48BD	S	1.000	\$62.023	11/26/2012	\$77.529
PART NAME: BATTERY, 48 GROUP (48H6/8448/48-91-60)		REPAIR: General Repair / Cranking System / Battery / Remove&Replace			
49275	S	1.000	\$21.720	11/26/2012	\$27.150
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
8891004	S	2.000	\$34.968	11/26/2012	\$87.420
PART NAME: AMBER MINI STROBE		REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace			
8891006	S	1.000	\$39.402	11/29/2012	\$49.253
PART NAME: WHITE MINI STROBE REPL EL3SNW		REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace			
47132575	NS	1.000	\$88.830	11/29/2012	\$111.038
PART NAME: MIRROR REAR VIEW		REPAIR: General Repair / Body / Mirror / Remove&Replace			

## WORK ORDER TOTALS

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TOTAL PARTS:	\$490.330	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$627.736	TOTAL MISC:	\$0.000	<b>TOTAL COST:</b>	<b>\$1,118.066</b>

## NOTES

276624 -

1-PMA 50 HRS. BUT (DRIVER REQUEST)

Perform PM-A

Changed engine oil/filter. Replaced air filter. Greased machine.

2-R/FRT. TIRE HAS A KNOT ON IT ESP

11/27/2012 @ 13:05:38 - I dont see a knot on tire, was this the right tractor? Tires low on air pressure, reset air pressure in both front tires

3-R/S MIRROR IS MISSING

Looks like mirror was hit by side mower. Mirror on order.

Installed new mirror.

R/S front strobe inop. Replaced rear strobes with amber strobes, replaced ! white rear and installed the other white one I removed in the front.

L/S rear turn signal light broken. Light assembly on order. Installed new light.

Slow start- found battery weak. Replaced battery. Checked charging system-OK.

R/S brake bulb burnt out. Replaced bulb- in shop supply.

524-7594 DAVID after tire repair give back to heavy/truck shop for mirror put in B status waiting on mirror

Repairs complete. 105

11/29/2012 @ 15:24:42

**WORK ORDER: 278765****UNIT NUMBER: 402360**

Work Order Status: C - C - CLOSED	Date In:	01/15/2013
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	01/18/2013

## UNIT NUMBER INFORMATION

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 477

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST
GAY	01/17/2013	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		0.72	\$46.930
BAKER	01/17/2013	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		3.47	\$190.697
RAMNATH	01/17/2013	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		3.15	\$173.269
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
CJ4G	NS	3.000	\$9.138	01/17/2013	\$34.269
PART NAME: ENGINE OIL 15W40 GAL CLOSED.		REPAIR: General Repair / Engine Block / System / Part Issue			
9276	NS	1.000	\$11.880	01/17/2013	\$14.850
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
84228488	NS	1.000	\$24.990	01/17/2013	\$31.238
PART NAME: OIL FILTER 57488		REPAIR: General Repair / Engine Block / Filter Engine O / Remove&Replace			
87329736	NS	1.000	\$8.230	01/17/2013	\$10.288
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
3765	NS	1.000	\$3.360	01/17/2013	\$4.200
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
5194879	NS	1.000	\$56.560	01/17/2013	\$70.700
PART NAME: HYDRAULIC FILTER, CARTRIDGE (D07510GAV)		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
7794	NS	1.000	\$11.800	01/17/2013	\$14.750
PART NAME: HYDRAULIC FILTER		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
5196842	NS	1.000	\$43.440	01/17/2013	\$54.300
PART NAME: CABIN AIR FILTER		REPAIR: General Repair / Body / Misc Parts / Remove&Replace			
5196842	NS	1.000	\$43.440	01/17/2013	\$54.300
PART NAME: CABIN AIR FILTER		REPAIR: General Repair / Body / Misc Parts / Remove&Replace			
33032	S	1.000	\$1.850	01/17/2013	\$2.313
PART NAME: FUEL FILTER		REPAIR: General Repair / Heating Vent / Resistor Blower / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$291.208	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$410.896	TOTAL MISC:	\$0.000	TOTAL COST:	\$702.104
NOTES					
278765 -					
PMC GPM Did PM-C and changed the cab filters, 323, 307					
CALL DAVIS 524-7594					



## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 283401					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	04/29/2013	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	05/02/2013	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 495		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
RAMNATH	04/30/2013	General Repair / Body / Mount Body / Diagnosis	1.57	\$86.289	
RAMNATH	05/01/2013	Add On / Mower / Frame Brush Hog / Repair	2.60	\$143.119	
BAKER	05/01/2013	Add On / Mower / Frame Brush Hog / Repair	0.82	\$44.989	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
5339-06	NS	2.000	\$4.710	05/01/2013	\$11.776
PART NAME: PAINT YELLOW JOHN DEERE		REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$11.776	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$274.397	TOTAL MISC:	\$0.000	TOTAL COST:	\$286.173
NOTES					
283401 -					
1-REAR DECK BRACKET BEND -Screw Missing ESP					
I removed the bracked the took it to the welding shop, The welder and I straightened the brackets and welded a strip od metal onto the brackets the strengthen them, I painted them to avoid rusting and Louis helped me instyall them.					
2-FRT. WIPER INOP.					
I removed the wipre arm and cleaned off the splines on the motor assemble, I installed the arm and adjusted it.					
398-4899					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 284054							
UNIT NUMBER: 402360							
Work Order Status: C - C - CLOSED						Date In:	05/14/2013
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP						Date Out:	05/23/2013
UNIT NUMBER INFORMATION							
YEAR: 2010		ORG: RETIRED FLEET			TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND		DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT			ENGINE SIZE: 90HP		
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation			TRANS: 16F-16R		
LICENSE: N/A		SITE: COF-SURPLUS LOCATION			FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972			ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor					METERS: Hour Meter - 517		
SUBLET REPAIRS							
VENDOR	PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST
SNIDER FLEET SOLUTIONS	\$0.00	\$180.00	\$22.50	218	05/15/2013	Road Call / Tire / Tube / Tire Industrial / Damaged tire	\$232.875
PARTS ISSUED							
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
16.9x34N		NS	1.000	\$669.380	05/22/2013	\$836.725	
PART NAME: TIRE-RADIAL				REPAIR: Road Call / Tire / Tube / Tire Industrial / Damaged tire			
16.9x34t		NS	1.000	\$85.000	05/22/2013	\$106.250	
PART NAME: TUBE				REPAIR: Road Call / Tire / Tube / Tire Industrial / Damaged tire			
WORK ORDER TOTALS							
TOTAL PARTS:		\$942.975	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: \$0.000	
TOTAL SUBLET:		\$232.875	SUBLET TAX:		\$0.000		
TOTAL LABOR:		\$0.000	TOTAL MISC:		\$0.000	TOTAL COST: \$1,175.850	
NOTES							
284054 -							
L/REAR TIRE CUT @ 1700 STATE ST. near DARBY ST.							
MIKE SENDING SYNIDER TIRE TO REPAIR							
398-4899 ESP							
05/20/2013 @ 15:13:36 Snider tire handled; waiting on invoice; Andrew							
05/22/2013 @ 10:19:09 stock in and issue tire and tube waiting on invoice for labor Andrew							
05/23/2013 @ 09:07:17 received invoice							
WORK ORDER: 284596							
UNIT NUMBER: 402360							
Work Order Status: C - C - CLOSED						Date In:	05/28/2013

## CITY OF RALEIGH VEHICLE FLEET SERVICES

## WORK ORDER DETAILS REPORT

p.19

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP

Date Out: 05/28/2013

## UNIT NUMBER INFORMATION

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 531

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
CRITTENDEN	05/28/2013	General Repair / Tire / Tube / Tire Industrial / Damaged tire	1.50	\$60.000
CRITTENDEN	05/28/2013	Add On / Wheel / Rim / Stud Wheel / Remove&Replace	0.50	\$20.000
AVILA	05/28/2013	General Repair / Air Conditioning / Misc Parts / Diagnosis	0.59	\$38.530

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
47126503	NS	2.000	\$9.300	05/28/2013	\$23.250
PART NAME: WHEEL STUD FRT		REPAIR: Add On / Wheel / Rim / Stud Wheel / Remove&Replace			
47126502	NS	2.000	\$5.110	05/28/2013	\$12.776
PART NAME: WHEEL NUT		REPAIR: Add On / Wheel / Rim / Stud Wheel / Remove&Replace			
1000X16N	NS	2.000	\$190.895	05/28/2013	\$477.238
PART NAME: NEW TIRE		REPAIR: General Repair / Tire / Tube / Tire Industrial / Damaged tire			

## WORK ORDER TOTALS

TOTAL PARTS:	\$513.264	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$118.530	TOTAL MISC:	\$0.000	<b>TOTAL COST:</b>	<b>\$631.794</b>

## NOTES

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

284596 -
1-REPLACE L/FRT. TIRE ESP
05/28/2013 @ 11:03:44 - installed 2 new tires on front, had to cut off old nuts off studs
ordered 2 studs and nuts to replace, NEED TO CALL DRIVER TO BRING TRACTOR BACK WHEN PARTS COME IN, installed temp studs and nuts
2-A/C NOT COOLING WHEN TEMP. IS HOT!
Found A/C condensor, radiator and hydraulic cooler plugged with debris. Blew out debris and A/C is cooling as designed.
driver cell # 919-398-4899 call when we get wheel studs
05/28/2013 @ 12:16:21 - NEW STUDS AND NUTS INSTALLED
Repairs complete. 105
05/28/2013 @ 12:59:14

WORK ORDER: 285430			
UNIT NUMBER: 402360			
Work Order Status: C - C - CLOSED	Date In:	06/14/2013	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	06/14/2013	

UNIT NUMBER INFORMATION			
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 570	

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
AVILA	06/14/2013	General Repair / Exhaust Engine / Clamp / Diagnosis	0.74	\$48.240

WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$48.240	TOTAL MISC:	\$0.000	TOTAL COST: \$48.240

NOTES				
285430 -				
MUFFLER CLAMP ESP				
Install and tighten clamps				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 285653					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	06/19/2013	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	06/26/2013	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 579		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BAKER	06/25/2013	General Repair / Engine / System / Diagnosis	2.29	\$125.809	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
49275	S	1.000	\$19.470	06/25/2013	\$24.338
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
86765	NS	1.000	\$9.520	06/25/2013	\$11.900
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
33032	S	1.000	\$1.850	06/25/2013	\$2.313
PART NAME: FUEL FILTER		REPAIR: General Repair / Heating Vent / Resistor Blower / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$38.551	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$125.809	TOTAL MISC:	\$0.000	TOTAL COST:	\$164.360
NOTES					
285653 -					
ENGINE IS SMOKING -Losing power when Accelerating ESP					
DAVID 524-7594					
Ck. engine for loss of power & found ---air filter stopped up , --- Change air filter,both fuel filters (parts) --Ordered parts--					
Engauge both mowers for load test & all seems ok 315					
PARKED ON SWS LOT ( NO SPACE BESIDE BLDG. 1 )					
WORK ORDER: 286635					
UNIT NUMBER: 402360					

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

Work Order Status: C - C - CLOSED	Date In: 07/10/2013
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out: 07/24/2013

UNIT NUMBER INFORMATION		
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 590

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
DEAN	07/10/2013	Road Call / Wheel / Rim / Nut Wheel / Repair	1.50	\$82.500
AVILA	07/24/2013	Add On / Wheel / Rim / Stud Wheel / Remove&Replace	1.74	\$113.178
AVILA	07/24/2013	Add On / Wheel / Rim / Nut Wheel / Remove&Replace	0.77	\$49.869

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
44011091	NS	6.000	\$4.360	07/23/2013	\$32.700
PART NAME: WASHER		REPAIR: General Repair / Wheel / Rim / Misc Parts / Remove&Replace			
12164224	NS	6.000	\$4.450	07/23/2013	\$33.378
PART NAME: NUT		REPAIR: General Repair / Wheel / Rim / Misc Parts / Remove&Replace			
5195908	NS	1.000	\$714.240	07/23/2013	\$892.800
PART NAME: DISC WHEEL		REPAIR: General Repair / Wheel / Rim / Misc Parts / Remove&Replace			
87651029	NS	6.000	\$5.430	07/23/2013	\$40.728
PART NAME: SCREW		REPAIR: General Repair / Wheel / Rim / Stud Wheel / Remove&Replace			

WORK ORDER TOTALS					
TOTAL PARTS:	\$999.606	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$245.547	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,245.153

NOTES
-------

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

286635 -
R/REAR TIRE has 5 WHEEL LUGS MISSING @ LAKE JOHNSON on the Dam ESP
DAVID 524-7594
07/10/2013 @ 10:43:18 remove several lug nuts from left rear and install on right rear to et tractor in; truck shop to check and replace wheel studs and lug nuts as needed; driver to bring in; mid 201
dept brought in for wheel studs and lug nut Truck shop to repair
Need: 6 studs, 6 lugnuts and inner rim. 105
07/17/2013 @ 10:53:4
Ordered rim and wheel parts Senter Tractor eta 7-19 ek
07/17/2013 @ 11:02:47
Installed new inner rim, replaced wheel studs and lugnuts.
Repair complete. 105
07/24/2013 @ 08:25:32

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 288352				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	08/12/2013
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	08/12/2013
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 605	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ZRILEY	08/12/2013	Road Call / Cranking System / System / Diagnosis	2.07	\$134.659
PARTS ISSUED				
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE
48BD	S	1.000	\$62.001	08/12/2013
PART NAME: BATTERY, 48 GROUP (48H6/8448/48-91-60)		REPAIR: General Repair / Cranking System / Battery / Remove&Replace		
WORK ORDER TOTALS				
TOTAL PARTS:	\$77.501	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$134.659	TOTAL MISC:	\$0.000	TOTAL COST: \$212.160
NOTES				
288352 -				
WILL NOT START, WON'T DO ANYTHING HAS A JUMP BOX, BUT WON'T JUMP				
AT CORNER OF M.L.KING BLVD AND DAWSON ST. ACROSS FROM KENNEDY CT				
DAVID 919-524-7594				
Could not find at first:				
Rmoved/replaced the battery:				
WORK ORDER: 289745				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	09/10/2013
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	09/17/2013
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	



W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509   PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 637

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ZRILEY	09/17/2013	General Repair / Air Conditioning / Misc Parts / Diagnosis	6.72	\$436.847

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
1-34-784-288	NS	1.000	\$55.280	09/17/2013	\$69.100
PART NAME: THERMOSTAT		REPAIR: General Repair / Air Conditioning / Misc Parts / Remove&Replace			
5162851	NS	13.000	\$2.854	09/17/2013	\$46.384
PART NAME: BUTTON-TRIM		REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			

WORK ORDER TOTALS					
TOTAL PARTS:	\$115.484	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$436.847	TOTAL MISC:	\$0.000	<b>TOTAL COST:</b>	<b>\$552.331</b>

NOTES
289745 -
A/C SHUT-OFF AFTER RUNNING 10-15 MINUTES
524-7594 DAVID ESP
Cleaned debri from radiator and the condensor: checked the cab filters ok;
Recovered freon to check the charge amount, unit has 2.4lbs froen, also leak tested and found no leaks, recharged and let system run appox 35-40min. unit stopped blowing air into cab. suspect the evaporator is freezing up;
Note had to reme the unit head liner and roof of unit to access the evaporator; as suspected the evap was frozen over. removed the thermostat that should have prevented unit from freezing and ordered per dana.
Ordered climate switch: mid117
09/17/2013 @ 10:41:59
Replaced the climate control thermostat, reinstalled the roof liner and top of unit , tested and unit works properly:
Repairs are completed
09/17/2013 @ 15:13:02 JU

<b>WORK ORDER: 294864</b>			
<b>UNIT NUMBER: 402360</b>			
Work Order Status: C - C - CLOSED	Date In:	12/31/2013	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	01/09/2014	

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

UNIT NUMBER INFORMATION						
YEAR: 2010		ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND		DEPT: ZZ100 6221 704010 509    PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP		
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A		SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor		METERS: Hour Meter - 658				
TECHNICIAN REPAIRS PERFORMED						
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST	
BAKER	01/07/2014	Add On / Light Emergency / ASM LightStrobe / Remove&Replace		1.78	\$98.008	
BAKER	01/08/2014	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		3.88	\$227.719	
PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
33032	S	1.000	\$1.300	01/07/2014	\$1.625	
PART NAME: FUEL FILTER		REPAIR:    General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace				
57794	NS	1.000	\$10.520	01/06/2014	\$13.150	
PART NAME: HYD FILTER		REPAIR:    General Repair / Hydraulic System / Filter Hydraul / Remove&Replace				
8891004	S	2.000	\$33.930	01/07/2014	\$84.826	
PART NAME: AMBER MINI STROBE		REPAIR:    General Repair / Light Emergency / Light Strobe / Remove&Replace				
7488	NS	1.000	\$6.460	01/08/2014	\$8.075	
PART NAME: OIL FILTER		REPAIR:    General Repair / Lubrication / Misc Parts / Remove&Replace				
49275	S	1.000	\$20.460	01/06/2014	\$25.575	
PART NAME: AIR FILTER		REPAIR:    General Repair / Cooling    Aux / Misc Parts / Remove&Replace				
33765	S	1.000	\$7.450	01/07/2014	\$9.313	
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR:    Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
WORK ORDER TOTALS						
TOTAL PARTS:	\$142.564	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000		
TOTAL LABOR:	\$325.727	TOTAL MISC:		\$0.000	<b>TOTAL COST:</b>	<b>\$468.291</b>
NOTES						

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

294864 -

PMC ESP

Started PMC , Ordered filters (dana ) COMPLETED PMC 315

DAVID 524-7594

OIL FILTER COMING FROM NAPA. ETA 1/7

Add on light repair----- Repair lights on rear , Replace strobe lights on front (parts)

John,

Please Update shows PMC 1/17/14 due ESP

WORK ORDER: 298470			
UNIT NUMBER: 402360			

Work Order Status: C - C - CLOSED	Date In:	03/20/2014
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP	Date Out:	03/20/2014

UNIT NUMBER INFORMATION			
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT	ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 660	

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
DOZIER	03/20/2014	General Repair / Tire / Tube / Tire Industrial / Replace L/Front	0.80	\$32.000

WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$32.000	TOTAL MISC:	\$0.000	TOTAL COST: \$32.000

NOTES
298470 -
L/frt. tire losing air
DAVID 524-7594 ESP
CHECKED TIRE UNDER WATER FOUND NO LEAK. 116
03/20/2014 @ 10:56:00

WORK ORDER: 298478				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	03/20/2014
Work Order Shop: R24 - R24 PRCR MARSH CREEK SHOP			Date Out:	03/20/2014
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 660	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000
NOTES				
298478 -				
NOT START -jc(HWY-A/LAWRENCE)				
JUMPED OFF & STARTED UP -jc				

WORK ORDER: 302486				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	06/06/2014
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	06/10/2014
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 750	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000
NOTES				
302486 -				
1- Sharpen or replace blades.				
2- Deck on boom won't turn on. KMU				
Lawrence - 919-398-4899				
Ck. power source for side mower & found drive broken				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 302934				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	06/17/2014
Work Order Shop: R24 - R24 PRCR MARSH CREEK SHOP			Date Out:	06/18/2014
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100 6221 704010 509 PARKS & REC - HIGHWAY MAINT		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 751	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000
NOTES				
302934 -				
NEED BLADES RAISED -kb(HWY-A/DAVID)				
LOWERED ROLLERS -ph				

WORK ORDER: 303982				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	07/08/2014
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	07/18/2014
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 787	

## CITY OF RALEIGH VEHICLE FLEET SERVICES

## WORK ORDER DETAILS REPORT

p.31

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST
RAMNATH	07/16/2014	Add On / Clutch / Pedal Clutch / Repair		1.60	\$103.819
RAMNATH	07/16/2014	General Repair / Engine / System / Diagnosis		3.46	\$225.138
RAMNATH	07/18/2014	General Repair / Light System / Misc Parts / Diagnosis		2.83	\$184.029
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
87356311	NS	1.000	\$86.900	07/18/2014	\$108.625
PART NAME: LAMP		REPAIR: General Repair / Light System / Light Asm / Remove&Replace			
886	NS	1.000	\$6.150	07/16/2014	\$7.688
PART NAME: BULB		REPAIR: General Repair / Light Emergency / Light Bar Asm Full / Remove&Replace			
49276	S	1.000	\$16.280	07/15/2014	\$20.350
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
33032	S	1.000	\$1.240	07/15/2014	\$1.550
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace			
49275	S	1.000	\$16.160	07/15/2014	\$20.200
PART NAME: AIR FILTER		REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace			
33765	S	1.000	\$7.450	07/15/2014	\$9.313
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
WORK ORDER TOTALS					
TOTAL PARTS:	\$167.726	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$512.986	TOTAL MISC:	\$0.000	TOTAL COST:	\$680.712
NOTES					

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

303982 -
1-Smoke from the exhaust (losing compression) ESP
I could not find a program to connect to the emc for the lose of compression complaint, I did change the fuel and air filters and ran the engine for a while, I also had John Utley test it and he said it was fixed
2-R/s low beam light & R/frt. strobe & correct wiring
I removed and replaced the blown day time running light bulb, I repaired the strobe light circuit, I ordered a left rear turn signal with Ed in parts.
07/16/2014 @ 08:05:46
I installed and tested the light.
I found the clutch pedal stop broken, I removed, drilled and extracted the bolt and repaired the stop.
07/16/2014 @ 10:06:53
David 524-7594
07/16/2014 @ 08:37:24
SHACK
LIGHT
SENER-DAVID
ETA 7-18 EK

WORK ORDER: 315364			
UNIT NUMBER: 402360			
Work Order Status: C - C - CLOSED		Date In:	01/29/2015
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP		Date Out:	02/03/2015

UNIT NUMBER INFORMATION			
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS- HIGHWAY MAINT-OPS	ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 862	

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
PENDERGRAFT	02/03/2015	General Repair / Blade / Cutting Edge Bl / Remove&Replace	1.50	\$82.500
PENDERGRAFT	02/03/2015	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	1.50	\$82.500



W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
CJ4-1	NS	12.000	\$1.716	02/03/2015	\$25.740
PART NAME: 15W40 CJ4 QTS			REPAIR: General Repair / Engine Block / System / Part Issue		
7488	NS	1.000	\$6.740	02/03/2015	\$8.425
PART NAME: OIL FILTER			REPAIR: General Repair / Engine Block / Filter Engine O / Remove&Replace		
33032	S	1.000	\$1.183	02/03/2015	\$1.479
PART NAME: FUEL FILTER			REPAIR: General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace		
49275	S	1.000	\$16.550	02/03/2015	\$20.688
PART NAME: AIR FILTER			REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace		
33765	S	1.000	\$7.730	02/03/2015	\$9.663
PART NAME: FUEL FILTER=86765=3765=BF7998			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		
WORK ORDER TOTALS					
TOTAL PARTS:	\$65.995	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$165.000	TOTAL MISC:	\$0.000	TOTAL COST:	\$230.995
NOTES					
315364 -					
PMC-----Done 540					
Replaced fuel filters					
Replaced air filter					
replace blades front and back-----Turned blades around and replaced cotter pins back blades are good tp					
KMU					
David morton - 524-7594					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 318212					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	03/16/2015	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	03/16/2015	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 862		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
RAMNATH	03/16/2015	Add On / Cranking System / Battery / Remove&Replace	0.77	\$50.230	
RAMNATH	03/16/2015	General Repair / Cranking System / Battery / Remove&Replace	0.01	\$0.360	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
48BD	S	1.000	\$62.000	03/16/2015	\$77.500
PART NAME: BATTERY, 48 GROUP (48H6/8448/48-91-60)		REPAIR: General Repair / Cranking System / Battery / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$77.500	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$50.590	TOTAL MISC:	\$0.000	TOTAL COST:	\$128.090
NOTES					
318212 -  Batteries gone. Won't crank. KMU  Checked and replaced the battery  03/16/2015 @ 14:22:36  Shack!!					
WORK ORDER: 319578					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	04/08/2015	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	04/27/2015	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 864

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
WHEELER	04/08/2015	General Repair / Air Conditioning / System / Diagnosis	1.37	\$89.179
MAYER	04/10/2015	General Repair / Air Conditioning / System / Diagnosis	3.20	\$207.948
MAYER	04/27/2015	General Repair / Air Conditioning / Compressor / Remove&Replace	5.65	\$367.296
MAYER	04/27/2015	General Repair / Air Conditioning / Dryer / Remove&Replace	1.03	\$66.930
MAYER	04/27/2015	General Repair / Air Conditioning / Valve Expansion / Remove&Replace	0.35	\$22.980
MAYER	04/27/2015	General Repair / Air Conditioning / Fitting A/C / Remove&Replace	0.01	\$0.600
MAYER	04/27/2015	General Repair / Air Conditioning / Fluid A/C / Fill Fluids	1.10	\$71.610

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
PAG150	S	4.000	\$6.182	04/08/2015	\$30.912
PART NAME: PAG OIL 150 (HIGH TEMP) CQP150-8D		REPAIR: General Repair / Air Conditioning / System / Part Issue			
87519620R	NS	1.000	\$470.000	04/09/2015	\$587.500
PART NAME: A/C COMPRESSOR		REPAIR: General Repair / Air Conditioning / Compressor / Remove&Replace			
5165615	NS	1.000	\$179.000	04/09/2015	\$223.750
PART NAME: RECEIVER DRYER		REPAIR: General Repair / Air Conditioning / Dryer / Remove&Replace			
FREON	S	4.000	\$3.530	04/27/2015	\$17.652
PART NAME: FREON - BILLED ONE POUND INCREMENTS		REPAIR: General Repair / Air Conditioning / Fluid A/C / Fill Fluids			
FREON	S	4.000	\$3.530	04/08/2015	\$17.652
PART NAME: FREON - BILLED ONE POUND INCREMENTS		REPAIR: General Repair / Air Conditioning / Fluid A/C / Fill Fluids			
923123	NS	1.000	\$9.530	04/08/2015	\$11.913
PART NAME: A/C STOP LEAK		REPAIR: General Repair / Air Conditioning / Misc Parts / Remove&Replace			
9966613	NS	1.000	\$216.000	04/09/2015	\$270.000
PART NAME: EXPANSION VALVE		REPAIR: General Repair / Air Conditioning / Valve Expansion / Remove&Replace			

WORK ORDER TOTALS					
TOTAL PARTS:	\$1,159.379	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$826.543	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,985.922

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

NOTES
<p>319578 -</p> <p>AC is a little cool, but not cool enough. KMU</p> <p>...dia. ac system...check pressure readings...no compressor operation...recovered freon and there was none in system...pulled vacuum and added freon...ran system for abit and added dye to system...ran for abit more and used black lite to verify issue...still no leak found...must be small leak...used sniffer, and sniffed entire system...finally found leak at compressor...will need compressor, dryer, and expansion valve...<b>parts have been ordered...426</b></p> <p><b>04/09/2015 @ 07:10:31</b></p> <p><b>ordered thru karen...</b></p> <p>recovered all freon again and replaced compressor, dryer and expansion valve...had to removed ac evaporator inorder to remove expansion valve...drew 30 minut vacuum and passed leak test...added 3.5 lbs of freon...ac is cold and pressure readings are good...all is good at this time...426</p> <p>Parts are here.</p> <p>04/09/2015 @ 12:13:29 KKW</p> <p>David M - 919-524-7594</p>

WORK ORDER: 322997					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	06/03/2015	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	06/04/2015	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 909		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
STINARD	06/03/2015	General Repair / Drive Cycle / Misc Parts / Repair	3.31	\$214.859	
STINARD	06/03/2015	Add On / Glass-Component / Blade W/S Wiper / Remove&Replace	0.31	\$20.350	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
31-20	S	2.000	\$2.133	06/03/2015	\$5.332
PART NAME: WIPER BLADE = 30-200		REPAIR: General Repair / Glass-Component / Blade W/S Wiper / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$5.332	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$235.209	TOTAL MISC:	\$0.000	TOTAL COST:	\$240.541
NOTES					
322997 -					
Lever that raises the mowing deck is very loose- TT took levers apart in cab to repalce missing screws , took cable end apart at hydaurlic valve found end was off cable , put end back on with locktite add justed cable till lever's worked correctly. mower lifts up and down ,good.					
Also took apart steering colum to repair shifter switch / head light switch. found screws missing , Replaced missing screws working good .					
ADD ON WIPER BLADES. R & I WIPER BLADES					
David Morton/ 919-524-7594					
WORK ORDER: 328887					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	09/09/2015	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	09/18/2015	
UNIT NUMBER INFORMATION					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS- HIGHWAY MAINT-OPS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1060

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
PULLEY	09/10/2015	General Repair / Arm Push-Pull / Misc Parts / Weld To Attach	1.88	\$103.230
PULLEY	09/18/2015	Add On / Welding Shop / MiscPartsNonVeh / Fabricate	0.53	\$29.360
WOOD	09/18/2015	General Repair / Blade / Blade Assembly / Remove&Replace	9.48	\$616.416

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
02976761	NS	2.000	\$103.150	09/15/2015	\$257.876
PART NAME: WELDMENT BRACKETS		REPAIR: General Repair / Mower / BearingMowSick / Remove&Replace			
703976	NS	2.000	\$118.460	09/15/2015	\$296.150
PART NAME: ROLLER BRG.		REPAIR: General Repair / Mower / BearingMowSick / Remove&Replace			
105319M	NS	76.000	\$1.250	09/15/2015	\$118.788
PART NAME: BLADE FLAIL		REPAIR: General Repair / Mower / Blade Mower Fla / Remove&Replace			
002037	NS	2.000	\$8.660	09/15/2015	\$21.650
PART NAME: SEAL		REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			

## WORK ORDER TOTALS

TOTAL PARTS:	\$694.464	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$749.006	TOTAL MISC:	\$0.000	<b>TOTAL COST:</b>	<b>\$1,443.470</b>

## NOTES

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

328887 -
1- Install new blades
Teeth to worn to flip.
Installed all new teeth.
2- Flare arm on right side needs new guard welded in. KMU
Repaired and reinstalled guard. 254
Roller bearings bad.
Ordered new roller bearings and hanger brackets and 76 flail blades from Dana
09/10/2015 @ 14:38:22
Installed new hangers and bearings.
Greased bearings.
Lawrence L - 919-398-4899
09/10/2015 @ 14:04:08 CUT OFF BENTARM AND WELDED IT BACK TOGETHER AND REINSTALLED. MID 254
DIXIE LAWN SERVICE BEARINGS- PLATES - FLAILS ETA 9-16-2015
09/14/2015 @ 09:15:19
BEARING - PLATES - BLADES ARE IN THE PARTS DEPARTMENT.
09/15/2015 @ 15:19:03
09/18/2015 @ 09:26:37 HELPED INSTALL ROLLER. MID 254

WORK ORDER: 330016			
UNIT NUMBER: 402360			
Work Order Status: C - C - CLOSED	Date In:	09/24/2015	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	09/29/2015	

UNIT NUMBER INFORMATION			
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS- HIGHWAY MAINT-OPS	ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 1077	

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ZRILEY	09/29/2015	General Repair / Engine / System / Diagnosis	3.03	\$121.159
ZRILEY	09/29/2015	Add On / Cooling Engine / Line Coolant / Remove&Replace	1.58	\$63.010
ZRILEY	09/29/2015	General Repair / Blade / Arm Blade Lift / Repair	2.25	\$89.959

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
49276	S	1.000	\$12.330	09/29/2015	\$15.413
PART NAME: AIR FILTER			REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace		
80653	NS	1.000	\$1.040	09/28/2015	\$1.300
PART NAME: 5/8" LINE SPLICE			REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace		
49275	S	1.000	\$16.550	09/29/2015	\$20.688
PART NAME: AIR FILTER			REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace		
33765	S	1.000	\$8.200	09/29/2015	\$10.250
PART NAME: FUEL FILTER=86765=3765=BF7998			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		
WORK ORDER TOTALS					
TOTAL PARTS:	\$47.651	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$274.128	TOTAL MISC:	\$0.000	TOTAL COST:	\$321.779
NOTES					
330016 -					
1- Starts fine and runs fine until it gets cutting. After around 30 minutes the rpms drop and it looses power.					
Found unit low on coolant.					
Found and repaired coolant leak.					
Found that the air filter was stopped completly up.					
Replaced air filter.					
Tractor had fault code for water in fuel.					
Replaced the fuel filter..					
Test drove and found no appearent problems..					
2- Flare arm bolt is backing out where it attaches to the body. KMU					
Repaired.					
Lawrence L - 919-247-6752					



## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

<b>WORK ORDER: 332171</b>		
<b>UNIT NUMBER: 402360</b>		
Work Order Status: C - C - CLOSED	Date In:	10/29/2015
Work Order Shop: R24 - R24 PRCR MARSH CREEK SHOP	Date Out:	10/29/2015

**UNIT NUMBER INFORMATION**

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS- HIGHWAY MAINT-OPS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1100

**PARTS ISSUED**

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
7488	NS	1.000	\$6.740	10/29/2015	\$6.740
PART NAME: FILTER OIL REPAIR: General Repair / Lubrication / Misc Parts / Remove&Replace					

**WORK ORDER TOTALS**

TOTAL PARTS:	\$6.740	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	<b>TOTAL COST:</b>	<b>\$6.740</b>

**NOTES**332171 -  
PMA

<b>WORK ORDER: 335474</b>		
<b>UNIT NUMBER: 402360</b>		
Work Order Status: C - C - CLOSED	Date In:	01/05/2016
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	01/06/2016

**UNIT NUMBER INFORMATION**

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS- HIGHWAY MAINT-OPS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1104

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TECHNICIAN REPAIRS PERFORMED							
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST		
ZRILEY	01/06/2016	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		4.03	\$161.029		
PARTS ISSUED							
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
83276		NS	1.000	\$16.000	01/06/2016	\$20.000	
PART NAME: AIR FILTER			REPAIR: General Repair / Engine Cycle / Filter Air / Remove&Replace				
84488		NS	1.000	\$8.580	01/06/2016	\$10.725	
PART NAME: OIL FILTER			REPAIR: General Repair / Engine Cycle / Filter Engine O / Remove&Replace				
33032		S	1.000	\$1.183	01/05/2016	\$1.479	
PART NAME: FUEL FILTER			REPAIR: General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace				
57794		NS	1.000	\$10.910	01/05/2016	\$13.638	
PART NAME: HYD FILTER			REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace				
CK4T		S	10.000	\$1.522	01/06/2016	\$19.030	
PART NAME: 15W40 OIL			REPAIR: General Repair / Hydraulic System / Fluid Hydraulic / Fill Fluids				
5196842		NS	1.000	\$49.500	01/05/2016	\$61.875	
PART NAME: CABIN AIR FILTER			REPAIR: General Repair / Body / Misc Parts / Remove&Replace				
49275		S	1.000	\$16.550	01/05/2016	\$20.688	
PART NAME: AIR FILTER			REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace				
33765		S	1.000	\$7.789	01/05/2016	\$9.736	
PART NAME: FUEL FILTER=86765=3765=BF7998			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
WORK ORDER TOTALS							
TOTAL PARTS:		\$157.171	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:		\$0.000	SUBLET TAX:		\$0.000		
TOTAL LABOR:		\$161.029	TOTAL MISC:		\$0.000	TOTAL COST:	\$318.200
NOTES							
335474 -  PMC KMU  changed engine iol and filter..  removed/replaced the hydrualic filter..  replaced both air filters..  replaced both fuel filters..  checked all lights..  greased..  David M - 524-7594							

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 338643						
UNIT NUMBER: 402360						
Work Order Status: C - C - CLOSED				Date In:	02/25/2016	
Work Order Shop: R24 - R24 PRCR MARSH CREEK SHOP				Date Out:	02/26/2016	
UNIT NUMBER INFORMATION						
YEAR: 2010		ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND		DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS		ENGINE SIZE: 90HP		
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A		SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor		METERS: Hour Meter - 1112				
PARTS ISSUED						
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
8891004		S	2.000	\$35.370	02/25/2016	\$70.740
PART NAME: AMBER MINI STROBE			REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace			
WORK ORDER TOTALS						
TOTAL PARTS:		\$70.740	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:		\$0.000	SUBLET TAX:		\$0.000	
TOTAL LABOR:		\$0.000	TOTAL MISC:		\$0.000	TOTAL COST: \$70.740
NOTES						
338643 -						
INSTALL LIGHTS						
INSTALLED NEW LED LIGHTS AND WIRED THEM UP, PH, DL, 2/26/16						

WORK ORDER: 342850					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	05/05/2016	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	05/06/2016	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 1161		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BAKER	05/06/2016	General Repair / Hydraulic System / Hose Hydraulic / Diagnosis	2.98	\$193.588	
BAKER	05/06/2016	General Repair / Hydraulic System / Hose Hydraulic / Remove&Replace	1.69	\$109.870	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
F387TC0639080808	NS	1.000	\$55.280	05/06/2016	\$69.100
PART NAME: HOSE		REPAIR: General Repair / Hydraulic System / Hose Hydraulic / Remove&Replace			
AW46T	S	14.000	\$2.768	05/06/2016	\$48.440
PART NAME: HYDRAULIC FLUID BULK QTS		REPAIR: General Repair / Lubrication / Fluid Auto Lube / Fill Fluids			
WORK ORDER TOTALS					
TOTAL PARTS:	\$117.540	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$303.458	TOTAL MISC:	\$0.000	TOTAL COST:	\$420.998
NOTES					
342850 -					
1- hydraulic hose leak TE					
Location B					
David 919-524-7594					
Tractor trapped in parking spot --- Locate keys for pickup -- Ck. hdy leak & found hdy. hose under tractor leaking ---Pull hose & parts dept. does not have the fittings -- Taking to cross to have new made -- Take hose to cross & have new one made (parts) Install new hose & find out what type of fluid system takes --- Fill w/ 26qts AW46 hdy.fld. ---Test & All seems ok 315					
Parked D section					

WORK ORDER: 346159				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	06/24/2016
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	06/24/2016
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: ZZ100- - PRCR - PARKS-HIGHWAY MAINT-OPS		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1219	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RAMNATH	06/24/2016	General Repair / Clutch / Misc Parts / Remove&Replace	0.12	\$7.710
SESSOMS	06/24/2016	General Repair / Tire / Tube / System / Diagnosis	0.60	\$33.000
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$40.710	TOTAL MISC:	\$0.000	TOTAL COST: \$40.710
NOTES				
346159 -				
Clutch pedal coming up to high. It looks like there's a return block missing TB				
Found the broken part in the cab				
Drilled and extracted the broken off bolt				
Installed the part with new bolt from the shop				
06/24/2016 @ 09:36:06 Meshach				
Gave key to Andrew for tire repair				
Check air pressure in L/F tire.				
Setction B				
Woody, 919-795-3788				
06/24/2016 @ 10:17:16 check tire pressure and aired them up didnt find a leak220				
WORK ORDER: 355006				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	11/03/2016

# CITY OF RALEIGH VEHICLE FLEET SERVICES

## WORK ORDER DETAILS REPORT

p.46

### W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP Date Out: 12/30/2016

UNIT NUMBER INFORMATION					
YEAR: 2010		ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: 100- - TRANS SVC - CONSTRUCTION-PARKS		ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 1342			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST
BAKER	11/04/2016	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		3.07	\$199.319
BAKER	11/04/2016	General Repair / Cab / Decals / Remove&Replace		0.59	\$38.040
BAKER	11/08/2016	General Repair / Fuel System / Filter Separato / Remove&Replace		0.95	\$61.519
BAKER	11/08/2016	General Repair / Fuel System / System / Diagnosis		0.76	\$49.420
BAKER	12/30/2016	General Repair / Cranking System / Battery / Remove&Replace		1.01	\$55.399
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
48BD	S	1.000	\$63.794	12/30/2016	\$79.743
PART NAME: BATTERY, 48 GROUP (48H6/8448/48-91-60)		REPAIR: General Repair / Cranking System / Battery / Remove&Replace			
33765	S	1.000	\$7.745	11/08/2016	\$9.681
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
CITY	S	2.000	\$3.658	11/04/2016	\$9.146
PART NAME: CITY DECAL 8"		REPAIR: General Repair / Body / Decals / Install			
84488	NS	1.000	\$8.580	11/04/2016	\$10.725
PART NAME: OIL FILTER		REPAIR: General Repair / Engine Cycle / Filter Engine O / Remove&Replace			
33032	S	1.000	\$1.182	11/08/2016	\$1.478
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace			
49275	S	1.000	\$16.550	11/03/2016	\$20.688
PART NAME: AIR FILTER		REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$131.461	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$403.697	TOTAL MISC:	\$0.000	TOTAL COST:	\$535.158
NOTES					

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

355006 -
pma due. MM
parked in D
919-524-7594 david
COMPLETED PMA --change oil,filter,air filter ,grease ,ck. over 315
Add on -- change city decals 315
Parked in sec. D
ADD ON: PICKED UP, STARTED DOWN THE ROAD, ALMOST DIED, JUST DID MAKE IT BACK HERE, POSSIBLE AIR IN FUEL LINE?
Ck. tractor fuel system out & could not find anything wrong except that it is low in fuel ,,,Change fuel filters & test drive ,operate mowers & All seems ok 315
(( Need to fuel up when they pick it up )) Parked in sec. D
Would not crank when came to pick up- Checked battery and it was bad. Replaced battery.

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 357740				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	12/21/2016
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	12/29/2016
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - CONSTRUCTION-PARKS		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1346	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RAMNATH	12/28/2016	General Repair / Fuel System / System / Diagnosis	1.87	\$121.638
SESSOMS	12/28/2016	General Repair / Tire / Tube / System / Diagnosis	0.80	\$32.000
PARTS ISSUED				
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE
33765	S	1.000	\$7.733	12/28/2016
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		
WORK ORDER TOTALS				
TOTAL PARTS:	\$9.666	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$153.638	TOTAL MISC:	\$0.000	TOTAL COST: \$163.304
NOTES				
357740 -				
leaking fuel by canister on side of motor. MM				
Repaired the fuel leak and tested the system				
12/28/2016 @ 09:52:41				
also check RF tire, leaks down overnight				
location D				
david. 919-524-7594				
12/28/2016 @ 12:56:21 didnt see anything left tire was low aired up see which one is low then go from there 220				
WORK ORDER: 358428				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	01/09/2017



# CITY OF RALEIGH VEHICLE FLEET SERVICES

## WORK ORDER DETAILS REPORT

p.49

### W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP

Date Out:

01/20/2017

#### UNIT NUMBER INFORMATION

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - CONSTRUCTION-PARKS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1346

#### TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
WOOD	01/17/2017	General Repair / Cranking System / System / Diagnosis	1.00	\$55.140
WOOD	01/17/2017	General Repair / Cranking System / Misc Parts / Wire Repair/Replace	2.00	\$110.140
WOOD	01/19/2017	General Repair / Cranking System / Misc Parts / Fabricate	1.58	\$86.929
WOOD	01/20/2017	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	11.47	\$630.833

#### PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
AW46T	S	4.000	\$1.619	01/20/2017	\$8.096
PART NAME: HYDRAULIC FLUID BULK QTS		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
CJ4G	NS	3.000	\$8.821	01/17/2017	\$33.078
PART NAME: ENGINE OIL 15W40 GAL CLOSED.		REPAIR: General Repair / Engine / System / Add Motor Oil			
83276	NS	1.000	\$16.970	01/13/2017	\$21.213
PART NAME: AIR FILTER		REPAIR: General Repair / Engine Cycle / Filter Air / Remove&Replace			
84488	NS	1.000	\$9.450	01/13/2017	\$11.813
PART NAME: OIL FILTER		REPAIR: General Repair / Engine Cycle / Filter Engine O / Remove&Replace			
86765	NS	1.000	\$12.070	01/13/2017	\$15.088
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
33032	S	1.000	\$1.182	01/13/2017	\$1.478
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace			
57794	NS	1.000	\$10.910	01/13/2017	\$13.638
PART NAME: HYD FILTER		REPAIR: General Repair / Hydraulic System / Filter Hydrauli / Remove&Replace			
86541699DS	NS	1.000	\$18.340	01/20/2017	\$22.925
PART NAME: HYD BRAKE OIL		REPAIR: General Repair / Hydraulic System / Misc Parts / Repair			
49275	S	1.000	\$16.550	01/13/2017	\$20.688
PART NAME: AIR FILTER		REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace			

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER TOTALS					
TOTAL PARTS:	\$148.017	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$883.042	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,031.059
NOTES					
358428 -  pmc is due, tractor is already here. MM  Tractor would not start.  Checked battery and cleaned connections, still no start.  Traced cable and found hidden ground point severely corroded.  Repaired, tractor starts well.  Battery hold down missing.  Fabricated new one.  Changed engine oil and filter.  Changed air filters.  Changed fuel filters.  Changed hydraulic filters.  Topped off fluids.  Greased tractor.  Lights good.  location D  Returned to C  david morton. 919-524-7594					
WORK ORDER: 363713					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED				Date In:	04/07/2017
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP				Date Out:	05/24/2017
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET			TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - CONSTRUCTION-PARKS			ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation			TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION			FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972			ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor				METERS: Hour Meter - 1351	

**1/15/2025 2:15:50 PM**

p.51

TECHNICIAN REPAIRS PERFORMED									
TECH		END DATE		REPAIR DESCRIPTION			HOURS	LABOR COST	
WOOD		05/18/2017		General Repair / PTO / Assembly / Diagnosis			9.40	\$516.776	
SUBLET REPAIRS									
VENDOR		PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST	
HAMILTON MACHINE WORKS		\$0.00	\$600.00	\$0.00	226	05/02/2017	General Repair / Hydraulic System / Misc Parts / Remove&Replace	\$690.000	
PARTS ISSUED									
PART NUMBER			S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST		
33032			S	1.000	\$1.181	05/24/2017	\$1.476		
PART NAME: FUEL FILTER					REPAIR: General Repair / Fuel SystemAux / Filter Fuel Pri / Remove&Replace				
02961452			NS	1.000	\$7.990	05/15/2017	\$9.988		
PART NAME: ORING					REPAIR: General Repair / Hydraulic System / Filter Hydrauli / Remove&Replace				
02961001			NS	1.000	\$105.990	05/15/2017	\$132.488		
PART NAME: HYD FILTER					REPAIR: General Repair / Hydraulic System / Filter Hydrauli / Remove&Replace				
AW46T			S	4.000	\$1.619	05/18/2017	\$8.096		
PART NAME: HYDRAULIC FLUID BULK QTS					REPAIR: General Repair / Lubrication / Fluid Auto Lube / Fill Fluids				
02957635			NS	1.000	\$103.990	04/21/2017	\$129.988		
PART NAME: COUPLER ROD HYDRAULIC					REPAIR: General Repair / Hydraulic System / Misc Parts / Remove&Replace				
24200			NS	1.000	\$6.447	05/03/2017	\$8.059		
PART NAME: THREADLOCKER BLUE					REPAIR: General Repair / Body / Misc Parts / Remove&Replace				
WORK ORDER TOTALS									
TOTAL PARTS:			\$290.095	PARTS TAX:			\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:			\$690.000	SUBLET TAX:			\$0.000		
TOTAL LABOR:			\$516.776	TOTAL MISC:			\$0.000	TOTAL COST:	\$1,496.871
NOTES									
363713 -									
was using flail mower, and it just quit working. MM									
may be an issue with the pto, also couldnt raise the mower, had to tie it up by hand									
Pump shaft splines sheared off.									
Ordered pump and drive shaft from Dana.									
04/07/2017 @ 14:11:06									
Vendor picked up pump for repair.									
04/11/2017 @ 12:32:32									
Installed new rod and pump.									
Hooked up lines and checked function.									

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

All is well.
Noticed hydraulic filter needs replacing,
Ordered from Dana
05/03/2017 @ 13:48:26
Wrong filter arrived.
Dana took pictures, inquiring with dealer.
05/16/2017 @ 14:38:20
Went and swapped out for correct filter.
Installed, topped off fluid.
All is well.
location D
Returned to D
david. 919-524-7594
CRAIG RIGHT OF WAY EQUIPMENT COUPLER ETA 4-19-2014. HAMILTONS MACHINE SHOP WILL MAKE ROD WHEN THEY HAVE THE COUPLER TO GO BY. Gregory Poole testing hydralulic pump.
04/11/2017 @ 15:43:49
Gregory Poole to rebuild hydraulic pump eta 4-20-17
04/13/2017 @ 17:21:46
CRAIG RIGHT OF WAY EQUIPMENT COUPLER HAS NOT ARRIVED SHOULD BE HERE BY THE END OF THIS WEEK.
04/18/2017 @ 08:48:34
GARY GREGORY POOLE BUSHINGS CAME IN WRONG TO REPAIR THE HYDRAULIC PUMP. SHOULD HAVE PUMP READY BY FRIDAY.
04/24/2017 @ 14:02:37
ROBBIE HAMILTONS MACHINE SHOP HAS NOT HAD TO MAKE ROD WILL TRY TO MAKE ROD ON MONDAY.
04/28/2017 @ 12:47:37
Robbie started making the rod today will be finished by lunch tomorrow.
05/01/2017 @ 15:49:31
KEN RIGHT OF WAY EQUIPMENT HYDRAULIC FILTER AND ORING ETA 5-9-2017
05/03/2017 @ 13:56:28
KEN RIGHT OF WAY EQUIPMENT HYDRAULIC FILTERS HAVE ARRIVED - STILL WAITING ON THE ORINGS.DF
05/10/2017 @ 13:23:32

WORK ORDER: 366933			
UNIT NUMBER: 402360			
Work Order Status:	C - C - CLOSED	Date In:	05/31/2017
Work Order Shop:	F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	06/26/2017
UNIT NUMBER INFORMATION			

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - CONSTRUCTION-PARKS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1357

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
WOOD	06/23/2017	General Repair / Mower / Misc Parts / Fabricate	3.02	\$196.068
WOOD	06/26/2017	General Repair / Mower / Belt Mow Sickel / Remove&Replace	11.58	\$752.936

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
A43	NS	2.000	\$10.000	05/31/2017	\$20.000
PART NAME: BELT		REPAIR: General Repair / Mower / Belt Mow Flail / Remove&Replace			
M35-15	NS	1.000	\$4.080	06/12/2017	\$5.100
PART NAME: STARTING FLUID		REPAIR: General Repair / Fuel System / Misc Parts / Remove&Replace			
c55b	NS	1.000	\$13.200	06/12/2017	\$16.500
PART NAME: belt		REPAIR: General Repair / Air Supply / Misc Parts / Remove&Replace			
NPL131	S	1.000	\$17.618	06/16/2017	\$22.023
PART NAME: LOCK NOT SPRAY = 179101		REPAIR: General Repair / Lubrication / Misc Parts / Install			
02031800	NS	1.000	\$0.990	06/21/2017	\$1.238
PART NAME: NUT FLAIL		REPAIR: General Repair / Mower / Misc Parts / Remove&Replace			
00752738	NS	1.000	\$2.990	06/21/2017	\$3.738
PART NAME: BOLT FLAIL		REPAIR: General Repair / Mower / Misc Parts / Remove&Replace			
000539S	NS	1.000	\$10.000	06/21/2017	\$12.500
PART NAME: SPRING FLAIL		REPAIR: General Repair / Mower / Misc Parts / Remove&Replace			
702747	NS	1.000	\$303.990	06/21/2017	\$379.988
PART NAME: IDLER ASSEMBLY		REPAIR: General Repair / Mower / Misc Parts / Remove&Replace			

WORK ORDER TOTALS					
TOTAL PARTS:	\$461.087	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$949.004	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,410.091

NOTES					
-------	--	--	--	--	--

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

366933 -
needs new belts installed on flail mower MM
parts already ordered belts
location B by gate
woody. 919-795-3788
Disassembled and found side mower hit something, mis-aligning belt.
Ordered new tensioner and hardware from Dana.
KEN RIGHT OF WAY EQUIPMENT ETA 7 - 16- 2017
06/13/2017 @ 17:19:06
CALLED PARTS HAVE NOT ARRIVED YET.DF
06/15/2017 @ 12:59:41
Received parts.
Fabricated new tensioner pivot pin.
Installed tensioner and belts.
Fabricated new cover mounts.
Cover was mangled. Straightened out and welded in bolt passage.
Installed on mower.
Parked in D

WORK ORDER: 369780			
UNIT NUMBER: 402360			
Work Order Status: C - C - CLOSED		Date In:	07/18/2017
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP		Date Out:	07/27/2017

UNIT NUMBER INFORMATION		
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - CONSTRUCTION-PARKS	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1364

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TECHNICIAN REPAIRS PERFORMED							
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST		
BAKER	07/24/2017	General Repair / Air Conditioning / System / Diagnosis		0.97	\$62.739		
BAKER	07/24/2017	General Repair / Air Conditioning / Condenser / Repair		3.92	\$254.488		
BAKER	07/27/2017	General Repair / Clutch / Pedal Clutch / Remove&Replace		3.17	\$206.098		
PARTS ISSUED							
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
5186201		NS	2.000	\$5.990	07/25/2017	\$14.976	
PART NAME: PIN			REPAIR: General Repair / Clutch / Pedal Clutch / Remove&Replace				
FREON		S	1.000	\$3.099	07/27/2017	\$3.874	
PART NAME: FREON - BILLED ONE POUND INCREMENTS			REPAIR: General Repair / Air Conditioning / Fluid A/C / Fill Fluids				
16043124		NS	10.000	\$1.100	07/25/2017	\$13.750	
PART NAME: SCREW			REPAIR: General Repair / Frame / Misc Parts / Remove&Replace				
87749703		NS	2.000	\$5.850	07/25/2017	\$14.626	
PART NAME: PIN			REPAIR: General Repair / Clutch / Misc Parts / Remove&Replace				
11063971		NS	1.000	\$1.950	07/25/2017	\$2.438	
PART NAME: CLIP			REPAIR: General Repair / Clutch / Misc Parts / Remove&Replace				
12647604		NS	10.000	\$0.590	07/25/2017	\$7.380	
PART NAME: WASHER			REPAIR: General Repair / Clutch / Misc Parts / Remove&Replace				
11193874		NS	10.000	\$0.540	07/25/2017	\$6.750	
PART NAME: WASHERS			REPAIR: General Repair / Exhaust Engine / Muffler Exhaust / Remove&Replace				
WORK ORDER TOTALS							
TOTAL PARTS:		\$63.794	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:		\$0.000	SUBLET TAX:		\$0.000		
TOTAL LABOR:		\$523.325	TOTAL MISC:		\$0.000	TOTAL COST:	\$587.119
NOTES							

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

369780 -

CLUTCH PEDAL POPPED ALL THE WAY UP AR

GAVE TECH A PEICE THAT CAME OFF ABOUT THE SIZE OF A PENCIL

Ck. clutch pedal out & Ordered parts (vaden)

07/18/2017 @ 15:22:05 315

ORDERED CLUTCH PEDAL PARTS FROM DAVE AT THE TRACTOR CENTER, ETA 7/21/17

07/18/2017 @ 15:15:19 VS

TWO OF THE CLUTCH PARTS ARE ON BACK ORDER AND WILL NOT ARRIVE UNTIL 7/24/17

07/21/2017 @ 13:45:31VS

AC NOT COOLING.

LOCATION D

CONTACT DAVID 919 524 7594

Ck. clutch pedal when it came in & found the stop & switch leg broken „Ordered clutch parts (vaden) 315

Ck. A/C system & found weak ,,, Ck. condensor & found stoppped up „Pull down & clean out,,Ck. pressures & top off freon 1/2 lb.--- Operate system & ck. All seems ok 315

Pull clutch pedal out & replace switch pin & stop „Reassemble & ck. -- All seems ok 315

Parked in sec. D

WORK ORDER: 380560				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	01/11/2018
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	01/24/2018
UNIT NUMBER INFORMATION				
YEAR: 2010		ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1398	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BAKER	01/24/2018	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	5.84	\$379.840



W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
CK4T	S	11.000	\$1.295	01/24/2018	\$17.809
PART NAME: 15W40 OIL			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		
83276	NS	1.000	\$17.850	01/24/2018	\$22.313
PART NAME: AIR FILTER			REPAIR: General Repair / Engine Cycle / Filter Air / Remove&Replace		
84488	NS	1.000	\$9.450	01/24/2018	\$11.813
PART NAME: OIL FILTER			REPAIR: General Repair / Engine Cycle / Filter Engine O / Remove&Replace		
57794	NS	1.000	\$10.910	01/23/2018	\$13.638
PART NAME: HYD FILTER			REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace		
49275	S	1.000	\$16.550	01/23/2018	\$20.688
PART NAME: AIR FILTER			REPAIR: General Repair / Cooling Aux / Misc Parts / Remove&Replace		
33765	S	1.000	\$7.731	01/23/2018	\$9.664
PART NAME: FUEL FILTER=86765=3765=BF7998			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		
WORK ORDER TOTALS					
TOTAL PARTS:	\$95.925	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000	
TOTAL LABOR:	\$379.840	TOTAL MISC:		\$0.000	TOTAL COST: \$475.765
NOTES					
380560 -  pmc ar  location d  contact david 919 524 7594  COMPLETED PMC ( oil,filters,grease,ck. over) 315  Parked in the beginning on sec D  called left vm  01/24/2018 @ 16:24:44					
WORK ORDER: 387031 UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED				Date In:	04/27/2018
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP				Date Out:	05/08/2018
UNIT NUMBER INFORMATION					
YEAR: 2010		ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: 100- - TRANS SVC - HIGHWAY MOWING		ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1409

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ZRILEY	04/30/2018	General Repair / Air Conditioning / System / Diagnosis	0.67	\$43.750
ZRILEY	04/30/2018	General Repair / Air Conditioning / Line Air Cond / Remove&Replace	3.34	\$217.078
ZRILEY	05/03/2018	General Repair / Air Conditioning / Misc Parts / Repair	4.31	\$280.399
ZRILEY	05/07/2018	General Repair / Air Conditioning / System / Fill Fluids	2.88	\$186.947
ZRILEY	05/08/2018	General Repair / Air Conditioning / System / PerformanceTest	0.66	\$42.760

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
FREON	S	4.000	\$3.269	05/08/2018	\$16.344
PART NAME: FREON - BILLED ONE POUND INCREMENTS		REPAIR: General Repair / Air Conditioning / Fluid A/C / Fill Fluids			
9827059	NS	1.000	\$1.350	05/07/2018	\$1.688
PART NAME: ORING		REPAIR: General Repair / Steering / Misc Parts / Remove&Replace			
14453283	NS	1.000	\$4.510	05/07/2018	\$5.638
PART NAME: O RING		REPAIR: General Repair / Steering / Misc Parts / Remove&Replace			
87487383	NS	1.000	\$106.200	05/07/2018	\$132.750
PART NAME: AC TUBE		REPAIR: General Repair / Steering / Misc Parts / Remove&Replace			

## WORK ORDER TOTALS

TOTAL PARTS:	\$156.420	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$770.934	TOTAL MISC:	\$0.000	<b>TOTAL COST:</b>	<b>\$927.354</b>

## NOTES

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

387031 -

a/c not cooling. MM

Recovered system and found no freon in system..

Tested for leaks and found line from the compressor leaking.

ordered line and replaced..

charge system 3.5 lbs freon and performed leak test..

No leaks found, system cooling great..

location D

919 524 7594

ordered ac compressor line from tractor center will be here in two days

05/03/2018 @ 10:42:39jc

WORK ORDER: 390937			
UNIT NUMBER: 402360			
Work Order Status: C - C - CLOSED		Date In:	06/29/2018
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP		Date Out:	07/16/2018

UNIT NUMBER INFORMATION		
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1409

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RAMNATH	06/29/2018	General Repair / Light System / Light Exterior / Repair	2.46	\$159.568
RAMNATH	07/02/2018	General Repair / Light System / Light Exterior / Remove&Replace	0.65	\$42.299
RAMNATH	07/02/2018	General Repair / Light System / Wiring Light / Wire Repair/Replace	4.81	\$312.826
RAMNATH	07/16/2018	General Repair / Exhaust Engine / Pipe Exhaust / Repair	4.90	\$318.507

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
H3	S	1.000	\$6.990	07/02/2018	\$8.738
PART NAME: HALOGEN SEAL BEAM H3B1 1255/H3			REPAIR: General Repair / Light System / Bulb Headlight / Remove&Replace		
cq-1893	NS	2.000	\$0.390	07/02/2018	\$0.976
PART NAME: mini bulb			REPAIR: General Repair / Engine Block / Filter Engine O / Remove&Replace		
7506	NS	2.000	\$0.560	07/05/2018	\$1.400
PART NAME: mini bulb			REPAIR: General Repair / Engine Block / Filter Engine O / Remove&Replace		
8891004	S	1.000	\$36.119	06/29/2018	\$45.149
PART NAME: AMBER MINI STROBE			REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace		
8891004	S	1.000	\$36.119	06/29/2018	\$45.149
PART NAME: AMBER MINI STROBE			REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace		
8891004	S	1.000	\$36.119	06/29/2018	\$45.149
PART NAME: AMBER MINI STROBE			REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace		
8891004	S	1.000	\$36.119	06/29/2018	\$45.149
PART NAME: AMBER MINI STROBE			REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace		
84357191	NS	1.000	\$351.000	07/16/2018	\$438.750
PART NAME: exhaust pipe			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
10902124	NS	10.000	\$0.480	07/16/2018	\$6.000
PART NAME: washer			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
17800374	NS	10.000	\$0.590	07/16/2018	\$7.380
PART NAME: washer			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
12644404	NS	10.000	\$0.920	07/16/2018	\$11.500
PART NAME: washer			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
16043424	NS	2.000	\$1.890	07/16/2018	\$4.726
PART NAME: SCREW			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
47128424	NS	1.000	\$12.870	07/16/2018	\$16.088
PART NAME: COLLAR			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
5182539	NS	1.000	\$225.000	07/16/2018	\$281.250
PART NAME: shield			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
5182538	NS	1.000	\$225.000	07/16/2018	\$281.250
PART NAME: shield			REPAIR: General Repair / Safety Interior / Misc Parts / Remove&Replace		
11193874	NS	2.000	\$0.540	07/16/2018	\$1.350
PART NAME: WASHERS			REPAIR: General Repair / Exhaust Engine / Muffler Exhaust / Remove&Replace		
WORK ORDER TOTALS					
TOTAL PARTS:	\$1,240.004	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$833.200	TOTAL MISC:	\$0.000	<b>TOTAL COST: \$2,073.204</b>

NOTES

390937 -

2 safety lights in the rear

check all safety lights

Troubleshoot system and found several electricla faults

Removed and replaced strobe lights

Removed and replaced work light buld

Removed and replaced turn signal

Rewired light circuit

Repaired light connectors

Repaired several power and ground connections

All systems work at this time

07/02/2018 @ 13:39:36

exhust pipe mealted lights exhust is to close to lights needs to be moved over

Removed the heat shield and inspected

Found exhaust pipe broken beyound repair

Ordered replacement parts with James

Removed and replaced the Exhaust pipe and heat shield

07/16/2018 @ 09:46:39

location D

contact danny

ORDERED EXHAUST FROM TRACTOR CENTER

07/05/2018 @ 08:14:26JC

WAS INFORMED YESTERDAY THAT EXHAUST SYSTEM WILL NOT BE AVAILBLE UNTIL 7/26/18

07/10/2018 @ 08:30:38JC

07/10/2018 @ 08:31:10JC

<b>WORK ORDER: 393996</b>			
<b>UNIT NUMBER: 402360</b>			

Work Order Status: C - C - CLOSED	Date In:	08/16/2018
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP	Date Out:	08/23/2018

UNIT NUMBER INFORMATION

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
------------	--------------------	------------------------------

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

MAKE: NEW HOLLAND	DEPT: 100- - MOWING	TRANS SVC - HIGHWAY	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor			METERS: Hour Meter - 1445

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
SESSOMS	08/16/2018	Road Call / Tire / Tube / System / Road Service	1.20	\$48.000
SESSOMS	08/16/2018	Road Call / Tire / Tube / Tire Industrial / Damaged tire	1.50	\$60.000
DOZIER	08/16/2018	Road Call / Tire / Tube / Tire Industrial / Damaged tire	1.50	\$60.000
SESSOMS	08/17/2018	Road Call / Tire / Tube / Tire Industrial / Repair	2.00	\$80.000

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
18.4x34t	NS	1.000	\$57.863	08/17/2018	\$72.329
PART NAME: TUBE		REPAIR: Road Call / Tire / Tube / Tire Industrial / Repair			
16.9x34N	NS	1.000	\$575.900	08/17/2018	\$719.875
PART NAME: TIRE-RADIAL		REPAIR: Road Call / Tire / Tube / Tire Industrial / Damaged tire			

WORK ORDER TOTALS					
TOTAL PARTS:	\$792.204	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$248.000	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,040.204

NOTES
393996 -
Road Call AR
left rear tire is going flat
location 1200 south saunders
driver said it was the side road over by ray price harley-davison
contact 919 524 7594
08/16/2018 @ 12:05:03 tire damaged odd tire size finally found tire in durham tire solutions tech meet sales person on leeville rd at location of another roadcall picked up tire and tube for tractor 220
08/16/2018 @ 14:10:56 replaced tire with new old tire damage
08/16/2018 @ 12:41:39 waiting on invoice for tire and tube tube bad
08/17/2018 @ 09:12:59 tire when flat had to carry another tube and install 220
08/17/2018 @ 13:56:52 received invoice
08/23/2018 @ 09:18:29 received invoice complete

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 395641				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	09/10/2018
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	09/10/2018
UNIT NUMBER INFORMATION				
YEAR: 2010		ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1465	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RAMNATH	09/10/2018	General Repair / Cranking System / Battery / Diagnosis	0.79	\$51.150
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$51.150	TOTAL MISC:	\$0.000	TOTAL COST: \$51.150
NOTES				
395641 -				
needs a battery and a battery post AR				
Checked and found the battery is good				
Found loose connection on the ground strap				
Repaired the connection and tested				
Equipment starts at this time				
09/10/2018 @ 15:02:54				
location c				
waiting				
WORK ORDER: 402530				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	01/07/2019
Work Order Shop: F12 - F12 FLEET COF LIGHT VEHICLE SHOP			Date Out:	01/10/2019
UNIT NUMBER INFORMATION				
YEAR: 2010		ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

MAKE: NEW HOLLAND	DEPT: 100- - MOWING	TRANS SVC - HIGHWAY	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor			METERS: Hour Meter - 1482

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BOND	01/09/2019	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	5.96	\$387.436
BOND	01/10/2019	Add On / Mower / Misc Parts / Repair	3.31	\$214.988

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
550236	NS	2.000	\$15.270	01/08/2019	\$30.540
PART NAME: FILTER AIR CABIN		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
49275	S	1.000	\$20.340	01/08/2019	\$25.425
PART NAME: AIR FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
CK4T	S	11.000	\$1.373	01/09/2019	\$18.876
PART NAME: 15W40 OIL		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
UTFT	S	14.000	\$2.855	01/09/2019	\$49.966
PART NAME: UNIVERSAL TRACTOR FLUID		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
9276	NS	1.000	\$13.500	01/08/2019	\$16.875
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
3765	NS	1.000	\$8.910	01/08/2019	\$11.138
PART NAME: FUEL FILTER		REPAIR: General Repair / Fuel System / Filter Fuel Pri / Remove&Replace			
57794	NS	1.000	\$12.390	01/07/2019	\$15.488
PART NAME: HYD FILTER		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
84841	NS	1.000	\$31.320	01/09/2019	\$39.150
PART NAME: HYDRAULIC FILTER		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
5194879	NS	1.000	\$61.880	01/10/2019	\$77.350
PART NAME: HYDRAULIC FILTER, CARTRIDGE (D07510GAV)		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
24200	NS	1.000	\$6.430	01/08/2019	\$8.038
PART NAME: THREADLOCKER BLUE		REPAIR: General Repair / Body / Misc Parts / Remove&Replace			

## MISCELLANEOUS COSTS

CODE	DESCRIPTION	POSTED DATE	MISC COST
SHOP FEE	Shop fee	01/07/2019	\$4.250

## WORK ORDER TOTALS



W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TOTAL PARTS:	\$292.846	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$602.424	TOTAL MISC:	\$4.250	<b>TOTAL COST:</b>	<b>\$899.520</b>

<b>NOTES</b>
402530 -  PMC. MM  430-----  found  Replace both engine air filters, fuel filter, oil filter, main hydraulic filter, steering hydraulic filter, and side mower hydraulic filter, checked alternator output and battery health then greased all fittings and linkages and checked for any needed repairs.COMPLETED  01/07/2019 @ 17:22:20 submitted parts request for needed filters.  01/07/2019 @ 18:06:00 Ordered all filters except for 94173 from Walker thru RPOD. Ordered filter 94173 from CQ fhru RPOD.---ge  01/09/2019 @ 10:37:57 had to order filters for steering and side mower  ADD ON 430----  side mower support bar only has 1 of 3 bolts on support bracket remaining, right side mower support bar bolts loose, realign brackets and replace missing bolts then use loc-tite on all fasteners. COMPLETED  section D  danny

<b>WORK ORDER: 408625</b>	
<b>UNIT NUMBER: 402360</b>	
Work Order Status: C - C - CLOSED	Date In: 04/18/2019
Work Order Shop: F12 - F12 FLEET COF LIGHT VEHICLE SHOP	Date Out: 05/06/2019

<b>UNIT NUMBER INFORMATION</b>		
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - MOWING	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1491

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TECHNICIAN REPAIRS PERFORMED						
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST	
SMITH	04/22/2019	General Repair / Air Conditioning / System / Diagnosis		1.50	\$97.500	
BATTISTEL	04/24/2019	Add On / Tire / Tube / Tire Industrial / Replace Front		2.00	\$80.000	
SMITH	04/25/2019	Add On / Body / Misc Parts / Diagnosis		0.50	\$32.500	
SMITH	04/25/2019	General Repair / Air Conditioning / Compressor / Remove&Replace		2.50	\$162.500	
SMITH	04/26/2019	General Repair / Air Conditioning / Dryer / Remove&Replace		1.00	\$65.000	
SMITH	04/26/2019	General Repair / Air Conditioning / System / PerformanceTest		0.50	\$32.500	
SMITH	04/26/2019	General Repair / Air Conditioning / Fluid A/C / Fill Fluids		1.00	\$65.000	
ROGERS	04/26/2019	General Repair / Air Conditioning / Fluid A/C / Fill Fluids		1.00	\$65.000	
SMITH	05/03/2019	Add On / Body / Misc Parts / Remove&Replace		2.50	\$162.500	
PARTS ISSUED						
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
1000X16N		NS	2.000	\$194.570	04/23/2019	\$486.426
PART NAME: NEW TIRE			REPAIR: Add On / Tire / Tube / Tire Industrial / Replace Front			
PAG100		S	1.000	\$6.741	04/25/2019	\$8.426
PART NAME: PAG OIL 100 CQP100-8D			REPAIR: General Repair / Air Conditioning / System / Part Issue			
87519620R		NS	1.000	\$390.000	04/24/2019	\$487.500
PART NAME: A/C COMPRESSOR			REPAIR: General Repair / Air Conditioning / Compressor / Remove&Replace			
87729381		NS	1.000	\$50.000	04/24/2019	\$62.500
PART NAME: LATCH HOOD			REPAIR: General Repair / Air Conditioning / Dryer / Remove&Replace			
5165615		NS	1.000	\$122.400	04/24/2019	\$153.000
PART NAME: RECEIVER DRYER			REPAIR: General Repair / Air Conditioning / Dryer / Remove&Replace			
FREON		S	2.000	\$3.210	04/26/2019	\$8.026
PART NAME: FREON - BILLED ONE POUND INCREMENTS			REPAIR: General Repair / Air Conditioning / Fluid A/C / Fill Fluids			
84291155		NS	1.000	\$101.700	05/06/2019	\$127.125
PART NAME: CAPPING			REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			
84288723		NS	1.000	\$88.100	05/06/2019	\$110.125
PART NAME: HANDLE			REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			
47130858		NS	1.000	\$20.790	05/06/2019	\$25.988
PART NAME: PIN			REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			
16689177		NS	5.000	\$3.510	05/06/2019	\$21.940
PART NAME: SCREW			REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			
84309099		NS	1.000	\$6.320	05/06/2019	\$7.900
PART NAME: ROD			REPAIR: General Repair / Frame / Misc Parts / Remove&Replace			

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
SHOP FEE	Shop fee		04/18/2019		\$4.250
WORK ORDER TOTALS					
TOTAL PARTS:	\$1,498.956	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$762.500	TOTAL MISC:	\$4.250	TOTAL COST:	\$2,265.706
NOTES					
408625 -					
----a/c not cooling. MM					
perform diag. for ac inop					
ordered parts should be in wed					
replace ac compressor					
replace ac dryer					
add oil pull a 30 minute vacume on system					
charge system with 2 lbs of freon					
perform performance test on system					
ac system is cooling as designed to =====409					
add on;-- needs front tires					
04/23/2019 @ 08:24:12 order tires swt eta wednesday					
04/23/2019 @ 14:40:03 tires are here					
Front tires have been put on --- had to use tire mounting compound to seat done 221.					
ADD ON-----has broken hood latch assy.					
waiting on hood latch to arrive					
04/26/2019 @ 08:02:58					
DAVE TRACTOR CENTER HAD TO ORDER HOOD PARTS FROM NEW HOLLAND. ETA 5-1-2019DF					
04/26/2019 @ 08:45:52 -----got latch assy. but awaiting for latch release handle assy. h.r.					
replace hood latch and put tool on key ring=====409					
section b					
05/03/2019 @ 14:39:04					
danny					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 412163					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	06/11/2019	
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	06/11/2019	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor			METERS: Hour Meter - 1505		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
DOZIER	06/11/2019	General Repair / Tire / Tube / Tire Industrial / Repair	1.00	\$40.000	
DEAN	06/11/2019	General Repair / Tire / Tube / Tire Industrial / Repair	1.00	\$65.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
16.9x34t	NS	1.000	\$68.950	06/11/2019	\$86.188
PART NAME: TUBE		REPAIR: General Repair / Tire / Tube / Tire Industrial / Repair			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION	POSTED DATE	MISC COST		
SHOP FEE	Shop fee	06/11/2019	\$4.250		
WORK ORDER TOTALS					
TOTAL PARTS:	\$86.188	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$105.000	TOTAL MISC:	\$4.250	TOTAL COST:	\$195.438
NOTES					
412163 -					
TIRE GOING DOWN ON RIGHT REAR					
checked tire out install new tube ok					
WORK ORDER: 425175					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	01/02/2020	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	01/24/2020	
UNIT NUMBER INFORMATION					

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1542

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RAMNATH	01/07/2020	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	2.37	\$170.360
RAMNATH	01/08/2020	Repaired From PM Service / Light System / Light Exterior / Diagnosis	7.80	\$561.493
RAMNATH	01/08/2020	General Repair / Fuel System / System / Diagnosis	2.13	\$153.080

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
CK4T	S	10.000	\$1.348	01/07/2020	\$17.520
PART NAME: 15W40 OIL		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
49275	S	1.000	\$27.720	01/07/2020	\$36.036
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
83276	NS	1.000	\$17.800	01/07/2020	\$23.140
PART NAME: AIR FILTER		REPAIR: General Repair / Engine Cycle / Filter Air / Remove&Replace			
84488	NS	1.000	\$9.400	01/07/2020	\$12.220
PART NAME: OIL FILTER		REPAIR: General Repair / Engine Cycle / Filter Engine O / Remove&Replace			
94128	NS	1.000	\$15.620	01/07/2020	\$20.306
PART NAME: HYDRAULIC FILTER		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
84841	NS	1.000	\$31.240	01/07/2020	\$40.612
PART NAME: HYDRAULIC FILTER		REPAIR: General Repair / Hydraulic System / Filter Hydraul / Remove&Replace			
8891004	S	1.000	\$36.130	01/08/2020	\$46.969
PART NAME: AMBER MINI STROBE		REPAIR: General Repair / Light Emergency / Light Strobe / Remove&Replace			
33765	S	1.000	\$8.180	01/07/2020	\$10.634
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			

## MISCELLANEOUS COSTS

CODE	DESCRIPTION	POSTED DATE	MISC COST
SHOP FEE	Shop fee	01/02/2020	\$4.250

## WORK ORDER TOTALS

TOTAL PARTS:	\$207.437	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
--------------	-----------	------------	---------	---------------------	---------

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$884.933	TOTAL MISC:	\$4.250	<b>TOTAL COST: \$1,096.620</b>

NOTES
425175 -  pmc AR  guard left off left in the truck  check gas float. the needle is moving  location c/d  contact david morton 919 524 7594  <b>Complaint:</b> pmc  <b>Cause:</b> Requirement  <b>Correction:</b> Did PMC  Ordered fitlers with vaiden (were not stock items)  Removed and replaced the filters  Parts:  <b>Complaint:</b> Found several lights out and horn inop during PMC  <b>Cause:</b> Electrical circuits fault, Faulty bulb, Blown fuse  <b>Correction:</b> Troubleshoot and repair electrical circuits for the strobe lights  Removed and replaced the faulty strobe lights  Checked the work lights and there was no power at the light itself  Checked the light fuses and they were good  Removed the steering cover to gain access to the multifunction switch  Removed the multifunction switch and tested the electrical point  Found power at a white/blue wire  Applied power to the other electrical points and only the horn worked  Traced out the harness and unplugged at the connection  Tested and got the same results as the switch  Found the fuse box cover and located the horn fuse  Removed and replaced the horn fuse which was blown  The lights worked after replacing the horn fuse  Installed all of the components that were remover for the repair  Parts:  <b>Complaint:</b> check gas float. the needle is moving  <b>Cause:</b> Unknown  <b>Correction:</b> Could not duplicate the complaint

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

The fuel guage reads accurately at this time

Removed the dash cluster

Unplugged and checked the connections at the back of the cluster

Everything looks good at the back to the cluster

Plugged in the connectors and installed the dash cluster

Parts:

leaving hours are 1542

WORK ORDER: 433758			
UNIT NUMBER: 402360			

Work Order Status: C - C - CLOSED	Date In:	06/18/2020
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	06/18/2020

UNIT NUMBER INFORMATION		
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1546

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
FANCHER	06/18/2020	Road Call / Unit Services / Complete Unit / Road Service	2.94	\$211.357

MISCELLANEOUS COSTS			
CODE	DESCRIPTION	POSTED DATE	MISC COST
SHOP FEE	Shop fee	06/18/2020	\$4.250

WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$211.357	TOTAL MISC:	\$4.250	TOTAL COST: \$215.607

NOTES
-------

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

433758 -

1. ROAD CALL. MM

2 battery dead will not start

Complaint: Will not start.

Cause: Negative cable connection with tractor frame poor.

Correction: Battery voltage at 12.88volts. I checked over/cleaned connections and found the negative battery cable was loosely connected with rusty washers on each side of the cable. I cleaned the contacts, stacked both washers on the top of the cable and tightened. Tractor starts easily now.

Parts: none 108

located at 1615 S. Wilmington st

key in it

danny

Complaint:

Cause:

Correction:

Parts:

WORK ORDER: 444212			
UNIT NUMBER: 402360			

Work Order Status: C - C - CLOSED	Date In:	12/04/2020
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP	Date Out:	12/09/2020

UNIT NUMBER INFORMATION			
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 1640	

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
DOZIER	12/04/2020	General Repair / Tire / Tube / System / Diagnosis	0.30	\$14.400
DOZIER	12/09/2020	Add On / Tire / Tube / Tire Industrial / Repair	0.50	\$24.000

MISCELLANEOUS COSTS			
CODE	DESCRIPTION	POSTED DATE	MISC COST
SHOP FEE	Shop fee	12/04/2020	\$4.250

WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000



W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$38.400	TOTAL MISC:	\$4.250	<b>TOTAL COST: \$42.650</b>

NOTES
444212 -  fixing a tire leak AR  left rear  valve stem is leaking  12/04/2020 @ 12:19:11  Turned in parts slip for tire tube  12/04/2020 @ 12:26:43 checked tire . tire is a inner tube typ tire. Need a tube in it. 116  12/09/2020 @ 08:49:56  Repaired tire no more leaks. Tire is holding air. Spoke with Dwaine  <a href="#">Tube taken off the WO per Patrick. CI</a>  <a href="#">12/09/2020 @ 09:17:41</a>  location shop  contact dwayne

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 445423				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	01/04/2021
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	01/07/2021
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1641	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
PENDERGRAFT	01/07/2021	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	1.00	\$79.000
MISCELLANEOUS COSTS				
CODE	DESCRIPTION		POSTED DATE	MISC COST
SHOP FEE	Shop fee		01/04/2021	\$4.250
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$79.000	TOTAL MISC:	\$4.250	<b>TOTAL COST: \$83.250</b>
NOTES				
445423 -				
pmc-----done 540 AR				
All fluids look good. Cleand out radiator screen				
location c/d				
contact dwayne				
Check over change fuilids / fliters as needed last PMC 100 hrs ago				
01/04/2021 @ 10:31:56 JH				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 446573				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	01/25/2021
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	01/26/2021
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1643	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
DOZIER	01/26/2021	General Repair / Tire / Tube / System / Diagnosis	0.30	\$14.400
DOZIER	01/26/2021	Add On / Tire / Tube / Tire Heavy / Diagnosis	0.60	\$28.800
MISCELLANEOUS COSTS				
CODE	DESCRIPTION		POSTED DATE	MISC COST
SHOP FEE	Shop fee		01/25/2021	\$4.250
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$43.200	TOTAL MISC:	\$4.250	TOTAL COST: \$47.450
NOTES				
446573 -				
1. left rear tire has a slow leak MM				
section C				
dwayne				
seperate ticket on mowing decks, both need pm				
01/26/2021 @ 09:39:07 found valve stem leaking. 116				
01/26/2021 @ 09:41:47 replaced valve stem after checking tire for leak. 116				
Leaving hours are 1643				
01/26/2021 @ 12:05:38 AR				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER: 448452					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	03/01/2021	
Work Order Shop: F12 - F12 FLEET COF LIGHT VEHICLE SHOP			Date Out:	03/02/2021	
UNIT NUMBER INFORMATION					
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING		ENGINE SIZE: 90HP		
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R		
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor		METERS: Hour Meter - 1651			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BOND	03/02/2021	General Repair / Cab / Decals / Remove&Replace	0.57	\$44.900	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
CITY2	S	2.000	\$8.399	03/01/2021	\$21.838
PART NAME: CITY DECAL 7" (SMALL)		REPAIR: General Repair / Cab / Decals / Remove&Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
SHOP FEE	Shop fee		03/01/2021		\$4.250
WORK ORDER TOTALS					
TOTAL PARTS:	\$21.838	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$44.900	TOTAL MISC:	\$4.250	TOTAL COST:	\$70.988
NOTES					
448452 -					
REPLACE DECALS H.R.					
430-----					
replaced decals, COMPLETED					
Flail mower on rear being repaired on w/o 421975 h.r.					

WORK ORDER: 452478				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	05/14/2021
Work Order Shop: F13 - F13 FLEET COF PM SERVICE AND TIRE SHOP			Date Out:	05/14/2021
UNIT NUMBER INFORMATION				
YEAR: 2010	ORG: RETIRED FLEET		TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING		ENGINE SIZE: 90HP	
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A	SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1665	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
PENDERGRAFT	05/14/2021	General Repair / Tire / Tube / System / Diagnosis	0.30	\$23.700
PENDERGRAFT	05/14/2021	Repaired From PM Service / Tire / Tube / Tire Industrial / Repair	0.90	\$71.100
MISCELLANEOUS COSTS				
CODE	DESCRIPTION		POSTED DATE	MISC COST
SHOP FEE	Shop fee		05/14/2021	\$4.250
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$94.800	TOTAL MISC:	\$4.250	TOTAL COST: \$99.050
NOTES				
452478 -				
WAITING/ MM				
COMPLAINT: LEFT FRONT TIRE HAS A SCREW IN IT				
CAUSE:				
CORRECTION:REPAIRED TIRE NO MORE LEAKS FOUND 540				
PARTS:				
BAY 20				
WORK ORDER: 456842				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	07/28/2021
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	08/11/2021
UNIT NUMBER INFORMATION				

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1703

## TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
LIANTONIO	07/30/2021	General Repair / Air Conditioning / System / Diagnosis	1.39	\$114.100
LIANTONIO	07/30/2021	General Repair / Air Conditioning / System / Leak Test	1.00	\$81.910
LIANTONIO	07/30/2021	General Repair / Air Conditioning / System / Inspect	1.04	\$85.009
PULLEY	08/02/2021	General Repair / Welding Shop / MiscPartsNonVeh / Fabricate	0.98	\$80.570
LIANTONIO	08/11/2021	General Repair / Air Conditioning / Evaporator / Remove&Replace	3.78	\$309.567
LIANTONIO	08/11/2021	Add On / Air Intake Engine / Filter Air / Remove&Replace	0.40	\$32.800
LIANTONIO	08/11/2021	Add On / Air Conditioning / Cab Air Filter / Remove&Replace	0.80	\$65.600

## PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
5194744	NS	1.000	\$484.000	08/11/2021	\$629.200
PART NAME: EVAPORATOR		REPAIR: General Repair / Air Conditioning / Evaporator / Remove&Replace			
550261	NS	2.000	\$15.990	08/03/2021	\$41.574
PART NAME: CABIN AIR FILTER		REPAIR: General Repair / Air Conditioning / Cab Air Filter / Remove&Replace			
9276	NS	1.000	\$14.320	08/03/2021	\$18.616
PART NAME: AIR FILTER		REPAIR: General Repair / Air Intake Engine / Filter Air / Remove&Replace			
49275	S	1.000	\$21.790	08/03/2021	\$28.327
PART NAME: AIR FILTER		REPAIR: General Repair / Engine Cycle / Filter Air / Remove&Replace			
FREON	S	4.000	\$2.725	08/11/2021	\$14.172
PART NAME: FREON - BILLED ONE POUND INCREMENTS		REPAIR: General Repair / Air Conditioning / Fluid A/C / Fill Fluids			
ELC50/50T	S	3.000	\$1.545	08/10/2021	\$6.027
PART NAME: ANTIFREEZE ELC		REPAIR: General Repair / Lubrication / Fluid Auto Lube / Fill Fluids			

## MISCELLANEOUS COSTS

CODE	DESCRIPTION	POSTED DATE	MISC COST
SHOP FEE	Shop fee	07/28/2021	\$4.250

## WORK ORDER TOTALS

TOTAL PARTS:	\$737.916	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
--------------	-----------	------------	---------	---------------------	---------

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$769.556	TOTAL MISC:	\$4.250	<b>TOTAL COST: \$1,511.722</b>

<b>NOTES</b>
456842 -  DAVID MORTON/ 919-524-7594 MR  <b>COMPLAINT:</b> A/C BLOWS WARM AND COOL INTERMITTENTLY BUT NOT COLD  <b>CAUSE:</b> ---Performed diag and found feon low -checked all hoses and lines and found evaporator at roof top leaking at expansion valve side of coils ----Also found cabin filters dirty ---ordred parts with Vadien -  07/30/2021 @ 13:28:08  <b>CORRECTION:</b> ---Replaced roof mounted evaporator assembly with expansion vavle and checked for any vacumm leaks and charged system with freon to capacity -----checked system operation is working as designed at this time blowing cold ----405-----Also replaced roof mounted cabin filters -405-----  <b>ADD-ON</b> --- Found engine air filter very dirty -ordred air filter with Vadien  07/30/2021 @ 13:28:59  -Replaced engine air filter assembly -405-----  Had to repair bent bravcket on rear of mower. 254  PARTS:  ORDERED EVAPORATOR AND EXPANSION VALVE FROM PREMIER EQUIP, ETA 8/11/21  08/03/2021 @ 10:45:26 VS  CABIN AIR FILTERS AND ENGINE AIR FILTERS ARE HERE  08/03/2021 @ 10:46:30 VS  PARKED IN: D

<b>WORK ORDER: 466153</b>			
<b>UNIT NUMBER: 402360</b>			
Work Order Status: C - C - CLOSED	Date In:	02/01/2022	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP	Date Out:	02/16/2022	

<b>UNIT NUMBER INFORMATION</b>		
YEAR: 2010	ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34
MAKE: NEW HOLLAND	DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP
MODEL: T5060	BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R
LICENSE: N/A	SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1
OPERATOR:	VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5
CLASS: Farm Tractor		METERS: Hour Meter - 1714

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST
BAKER	02/16/2022	Add On / Cranking System / Battery / Diagnosis		1.12	\$91.727
BAKER	02/16/2022	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform		3.94	\$322.943
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
33032	S	1.000	\$1.880	02/07/2022	\$2.444
PART NAME: FUEL FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
33765	S	1.000	\$8.335	02/07/2022	\$10.836
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
49275	S	1.000	\$30.210	02/08/2022	\$39.273
PART NAME: AIR FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
7794	NS	1.000	\$20.200	02/08/2022	\$26.260
PART NAME: HYDRAULIC FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
9276	NS	1.000	\$19.850	02/08/2022	\$25.805
PART NAME: AIR FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
7488	NS	1.000	\$11.570	02/08/2022	\$15.041
PART NAME: OIL FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
84841	NS	2.000	\$30.910	02/08/2022	\$80.366
PART NAME: HYDRAULIC FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
SHOP FEE	SHOP FEE		02/01/2022		\$4.250
WORK ORDER TOTALS					
TOTAL PARTS:	\$200.025	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$414.670	TOTAL MISC:	\$4.250	TOTAL COST:	\$618.945
NOTES					
PREV. MAIN. - DAVID MORTEN 919-691-3820 COMPLAINT: PMC PAST DUE PMC parts Ordered 2/7/2022 7:24:04 AM JH PARKED: C ; PMC - COMPLAINT: PMC CAUSE: PMC Due CORRECTION: Performed PMC. Parked in section C. 10:41:26 AM 2/16/2022 ; Cranking System - COMPLAINT: Tractor Need Jump Starting CAUSE: N/A CORRECTION: Jump started and brought into shop. Allowed to run and charge. Alternator charging @ 14.12 volts. 10:54:39 AM 2/16/2022					
WORK ORDER: 479749					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED				Date In:	01/25/2023
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP				Date Out:	02/01/2023



## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

UNIT NUMBER INFORMATION					
YEAR: 2010		ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND		DEPT: 100- - MOWING	TRANS SVC - HIGHWAY		
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation		TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION		FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972		ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor		METERS: Hour Meter - 1744			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BAKER	01/25/2023	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	3.29	\$270.122	
BAKER	02/01/2023	Repaired From PM Service / Mower / Blade Mower Fla / Remove&Replace	3.54	\$289.961	
BAKER	02/01/2023	General Repair / Blade / Blade Assembly / Diagnosis	0.01	\$0.729	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
33765	S	1.000	\$8.335	01/25/2023	\$10.836
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
49275	S	1.000	\$24.130	01/25/2023	\$31.369
PART NAME: AIR FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
49276	S	1.000	\$15.860	01/25/2023	\$20.618
PART NAME: AIR FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
123	S	1.000	\$8.558	01/25/2023	\$11.125
PART NAME: GREASE BLUE		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
7794	NS	1.000	\$22.690	01/25/2023	\$29.497
PART NAME: HYDRAULIC FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
7488	NS	1.000	\$13.000	01/25/2023	\$16.900
PART NAME: OIL FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
102670	NS	10.000	\$3.990	01/31/2023	\$51.870
PART NAME: HARDENED PIN		REPAIR: Repaired From PM Service / Mower / Blade Mower Fla / Remove&Replace			
100761	NS	10.000	\$11.489	01/31/2023	\$149.360
PART NAME: RING COMPLETE		REPAIR: Repaired From PM Service / Mower / Blade Mower Fla / Remove&Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
SHOP FEE	SHOP FEE		01/25/2023		\$4.250

# CITY OF RALEIGH VEHICLE FLEET SERVICES

## WORK ORDER DETAILS REPORT

p.82

### W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

WORK ORDER TOTALS				
TOTAL PARTS:	\$321.575	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$560.812	TOTAL MISC:	\$4.250	<b>TOTAL COST: \$886.637</b>
NOTES				
PM C, CK MISSING BLADES - David Morton 919-524-7594 Concern: PM C Cause: Due 02-16-2023 Correction: completed pmc,,grease,oil,filters,general condition ect. Concern: Customer states check, blades are missing. Cause: broken off Correction: ck. drum for missing blades ,, found several gone ,,ordered blades,clevis & pins,, install new blades on missing stations & replace damaged blades Parked in lot D/E Ready for pick up. 2/1/2023 3:14:18 PM ; PARTS - I HAVE THE CLEVIS AND CLEVIS PINS ORDERED FROM RIGHT OF WAY EQUIPMENT. ALAMO SHOWED THEY WHERE INSTOCK SO THEY SHOULD BE HERE IN ABOUT A WEEK TIME. 8:00:51 AM 1/27/2023 JC				
WORK ORDER: 489643				
UNIT NUMBER: 402360				
Work Order Status: C - C - CLOSED			Date In:	09/19/2023
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	11/30/2023
UNIT NUMBER INFORMATION				
YEAR: 2010		ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34	
MAKE: NEW HOLLAND		DEPT: 100- - MOWING	ENGINE SIZE: 90HP	
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R	
LICENSE: N/A		SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1	
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5	
CLASS: Farm Tractor			METERS: Hour Meter - 1785	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BLALOCK	11/27/2023	General Repair / Mower / Misc Parts / Repair	5.00	\$410.000
BLALOCK	11/29/2023	General Repair / Mower / Frame Brush Hog / Repair	11.70	\$959.490
BLALOCK	11/29/2023	General Repair / Blade / Blade Assembly / Diagnosis	2.00	\$164.000
BLALOCK	11/30/2023	General Repair / Exterior Metal / Guard / Diagnosis	2.53	\$207.574
BLALOCK	11/30/2023	General Repair / Mower / Bearing MowFlai / Diagnosis	7.77	\$637.368

## W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
703695	NS	1.000	\$274.400	11/20/2023	\$356.720
PART NAME: BEARING ASSEMBLY INNER			REPAIR: General Repair / Mower / Bearing MowFlai / Diagnosis		
704305	NS	1.000	\$355.050	11/20/2023	\$461.565
PART NAME: BEARING ASSEMBLY OUTER			REPAIR: General Repair / Mower / Bearing MowFlai / Diagnosis		
19H3239	NS	20.000	\$1.950	11/20/2023	\$50.700
PART NAME: CAP SCREW			REPAIR: General Repair / Blade / Blade Assembly / Diagnosis		
107256	NS	1.000	\$693.390	11/20/2023	\$901.407
PART NAME: FOOTGUARD 74			REPAIR: General Repair / Blade / Blade Assembly / Diagnosis		
000702	NS	1.000	\$74.260	11/20/2023	\$96.538
PART NAME: BELT SET			REPAIR: General Repair / Blade / Blade Assembly / Diagnosis		
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
SHOP FEE	SHOP FEE		09/19/2023		\$4.250
WORK ORDER TOTALS					
TOTAL PARTS:	\$1,866.930	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$2,378.432	TOTAL MISC:	\$4.250	TOTAL COST:	\$4,249.612
NOTES					
BEARINGS IN SIDE MOWING DECK, MOWER GUARD/SHIELD ON SIDE DEC - DROP OFF WILLIE MORTON David Morton 919-524-7594 11/30/2023 4:01:06 PM PP READY FOR PICK UP. JMR. CONCERN: BEARNINGS IN SIDE MOWING DECK NEED REPLACING CORRECTION: Removed both side bearings and replaced with new. Both side bearings were seized inside the mower and barrel. Also the belts on the inside bearing were replaced with new. CONCERN: MOWER GUARD OR SHIELD ON SIDE DECK NEEDS REPLACING CORRECTION: removed side mower guard and replaced with new. All bolts had to be cut off due to rust and wear. Replaced all bolts with new. 0363 **All mower parts on order. 0363*** FUEL MASTER 1766 LOT C 11/30/2023 12:30:55 PM ; PARTS - ALL THE SIDE MOWER PARTS HAVE BEEN ORDERED FROM JAMES RIVER NONE OF THESE PARTS ARE STOCKING AT JAMES RIVER SO THEY HAD TO BE ORDERED FROM ALAMO DIRECTLY THE ETA ON THESE PARTS IS 11/1/23 THESE PARTS WHERE ORDERED ON 10/2/23 JC 10/24/2023 8:04:42 AM ***update****ETA 11/17/23 BERNITA					

WORK ORDER: 494856					
UNIT NUMBER: 402360					
Work Order Status: C - C - CLOSED			Date In:	01/31/2024	
Work Order Shop: F11 - F11 FLEET COF HEAVY VEHICLE SHOP			Date Out:	02/26/2024	
UNIT NUMBER INFORMATION					
YEAR: 2010		ORG: RETIRED FLEET	TIRE SIZE: 10.00-16, 16.9-34		
MAKE: NEW HOLLAND		DEPT: 100- - TRANS SVC - HIGHWAY MOWING	ENGINE SIZE: 90HP		
MODEL: T5060		BILL CODE: 2-FuelMarkup, Operation	TRANS: 16F-16R		
LICENSE: N/A		SITE: COF-SURPLUS LOCATION	FUEL TYPE: B, D, O, AW46T, CK4T, UTFT, ELC50/50T, CJ4-1		
OPERATOR:		VIN/SERIAL NUMBER: ZAJH05972	ASSET AVAIL CODE: Regular 8-5		
CLASS: Farm Tractor		METERS: Hour Meter - 1785			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
NORTON	02/09/2024	Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform	2.68	\$128.400	
BAKER	02/26/2024	General Repair / Hydraulic System / System / Repair Leak	6.34	\$519.516	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
33765	S	1.000	\$9.950	02/12/2024	\$12.935
PART NAME: FUEL FILTER=86765=3765=BF7998		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
7794	NS	1.000	\$27.470	02/12/2024	\$35.711
PART NAME: HYDRAULIC FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
7488	NS	1.000	\$14.950	02/12/2024	\$19.435
PART NAME: OIL FILTER		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM C Service / Perform			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
SHOP FEE	SHOP FEE		01/31/2024		\$4.250
WORK ORDER TOTALS					
TOTAL PARTS:	\$68.081	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$647.916	TOTAL MISC:	\$4.250	TOTAL COST:	\$720.247
NOTES					
PM C - DROP OFF D. DEAN 2/26/2024 8:23:32 AM emailed ready for pick up. JMR. CONCERN: PM C CORRECTION: PMC completed 1885 ADD ON: HAS A HYD LEAK NEAR HOUSING ON REAR OF TRACTOR LEAK COMING FROM HYD FILTER HOUSING CAP 2 BOLTS HAVE BEEN STRIPPED OUT -- ck. for leak on housing & found the hdy. filter housing leaking ,, remove cap from housing ,, replace o=ring ,, drill & tap bottom housing to get top to seal ,, install top & secure ,, test for leak & none found FUEL MASTER 1766 LOT C 2/26/2024 8:16:29 AM					

W300d - WorkOrderDetailsByDate

1/15/2025 2:15:50 PM

REPORT PARAMETERS:

Time Zone:	Eastern Standard Time
Start Date:	01/01/1993
End Date:	01/15/2025
Organization:	All Values
Department:	All Values
Unit Number:	402360
Maint Shop:	All Values
Labor Hours:	Actual Hours
Page Breaks:	No
Display Unit Cost or True Cost or Issue Price:	True Cost

REPORT VERSIONS:

Report Version:	20211207.2000
Script Version:	20211207.1600