








INSPECTION REPORT



PARCS Ltd.			
Certificate:	21-508766	Customer:	KAWARTHA PINE RIDGE DISTRICT S. B.
Equipment Id:	N/A	Location:	CRESTWOOD S.S.
Sales Order:	OP21-2023	Address:	1885 Sherbrooke Street West Peterborough ONTARIO K9J 6X4
CONTACT: CAROLEE MELVANIN		PHONE: 705-742-9773 EXT. 2153	EMAIL: carolee_melvanin@kprdsb.ca
DATA: Shop Equipment Assessment			
TYPE	METAL LATHE	SHOP TYPE	MACHINE
MAKE	STANDARD MODERN	MODEL	11" SERIES 2000
SERIAL NO.	U1146	ID NO.	N/A
ROOM NO.	B111	MFG DATE	N/A
LOCATION	N/A	MANUAL AVAILABLE	N/A
MOTOR HP	N/A	SAFETY PLACARD	YES
VOLTAGE	220V	LOCKOUT TYPE	LOCAL DISCONNECT
COLOUR CODING	N/A		
INSPECTION POINTS			
Inspection Point	Status	Repairs	Comments
ELECTRICAL (OKAY)			NO FAULTS NOTED
LIGHTING (OKAY)			NO FAULTS NOTED
EMERGENCY STOP (OKAY)			NO FAULTS NOTED
START BUTTON (OKAY)			NO FAULTS NOTED
DISCONNECT SWITCH (OKAY)			NO FAULTS NOTED
HOSES (N/A)			DOES NOT APPLY
GAUGES/REGULATORS (N/A)			DOES NOT APPLY
DOOR PANEL (NOT OKAY)			TOOL TIGHT FASTENER REQUIRED AT TOP COVER; TOOL TIGHT REQ. DOOR IS NOT EQUIPPED WITH INTERLOCK;
GUARDING (OKAY)			NO FAULTS NOTED
SAFETY DEVICES (N/A)			DOES NOT APPLY
GUIDES (OKAY)			NO FAULTS NOTED
BRAKE (N/A)			DOES NOT APPLY
GENERAL DAMAGE/WEAR (OKAY)			NO FAULTS NOTED
LEVEL (OKAY)			NO FAULTS NOTED
CURTAINS/SCREEN (N/A)			DOES NOT APPLY
CONTROLS (OKAY)			NO FAULTS NOTED
OPERATING POSITION (OKAY)			NO FAULTS NOTED
<p>All lifting devices which contain the SAFE FOR USE or CERTIFIED ICON have been thoroughly examined by a competent person to determine it capability of handling the maximum load as rated, as required by the OHSA Reg. 851-51(1)(b)</p> <p>This inspection is valid for work which was specifically requested at time of inspection only. All certificates are a result of work performed in conformance with applicable specifications and standards to the best of our ability and intent. However, PARCS Ltd. will not be responsible for deviations within the normal limits of accuracy, nor will it be held responsible for issues arising from incorrect operation or use of equipment in accordance with standard practices. PARCS Ltd., its owners, affiliates and employees will not be held liable for any failure, downtime, or injury as a result of this inspection report or work performed on this equipment.</p>			

INSPECTION REPORT








PARCS

PARCS Ltd.			
Inspection Point	Status	Repairs	Comments
HYDRAULICS (N/A)	<input type="radio"/>		DOES NOT APPLY
MECHANICAL (OKAY)	<input checked="" type="radio"/>		NO FAULTS NOTED
FRAME/BASE (OKAY)	<input checked="" type="radio"/>		NO FAULTS NOTED
<div><div><u>Status: NOT SAFE</u></div></div>			
Technician: Jonathan Evans		Signature: 	Date: Jul 06, 2021
HAZARD CLASS ICON LEGEND: <div><div> REMOVE FROM SERVICE, DO NOT USE UNTIL REPAIRED</div><div> CAUTION - RECOMMEND IMMEDIATE REPAIRS</div><div> MONITOR - SCHEDULE MAINTENANCE AT NEXT POSSIBLE INTERVAL</div><div> OK - MONITOR</div></div>			

All lifting devices which contain the SAFE FOR USE or CERTIFIED ICON have been thoroughly examined by a competent person to determine its capability of handling the maximum load as rated, as required by the OHSA Reg. 851-51(1)(b)

This inspection is valid for work which was specifically requested at time of inspection only. All certificates are a result of work performed in conformance with applicable specifications and standards to the best of our ability and intent. However, PARCS Ltd. will not be responsible for deviations within the normal limits of accuracy, nor will it be held responsible for issues arising from incorrect operation or use of equipment in accordance with standard practices. PARCS Ltd., its owners, affiliates and employees will not be held liable for any failure, downtime, or injury as a result of this inspection report or work performed on this equipment.

REPORT FINDINGS

PARCS Ltd.					
Customer:	KAWARTHA PINE RIDGE DISTRICT S. B.	Equipment Tag:	N/A		
Location:	CRESTWOOD S.S.	Overall Status:	NOT SAFE		
Certificate #:	21-508766	Inspection by:	Jonathan Evans		
Item Type:	Shop Equipment Assessment	Date:	Jul 06, 2021		
CONTACT: CAROLEE MELVANIN		PHONE: 705-742-9773 EXT. 2153	EMAIL: carolee_melvanin@kprdsb.ca		
Inspection Point	Deficiency	Hazard Class	Relevant Code/Standard	Section	Wording of Standard Code
DOOR PANEL (NOT OKAY) 	TOOL TIGHT FASTENER REQUIRED AT TOP COVER; TOOL TIGHT REQ. DOOR IS NOT EQUIPPED WITH INTERLOCK;		CSA Z432-16 Safeguarding of Machinery		
<div><i><u>Status: NOT SAFE</u></i></div>					
HAZARD CLASS ICON LEGEND:					
 REMOVE FROM SERVICE, DO NOT USE UNTIL REPAIRED		 MONITOR - SCHEDULE MAINTENANCE AT NEXT POSSIBLE INTERVAL			
 CAUTION - RECOMMEND IMMEDIATE REPAIRS		 OK - MONITOR			